

Tooltron - Bug #1057

yellow warning light blinks too slowly

01/27/2010 08:19 PM - Brad Neuman

Status:	Fixed	Start date:	01/27/2010
Priority:	Normal	Due date:	
Assignee:	Kevin Woo	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:			
Description			

History

#1 - 01/28/2010 02:03 PM - Kevin Woo

- Status changed from Assigned to Fixed

Dropped to 200ms in the code using _delay_ms