

## Colony Scout - Bug #1440

### value change R8 and R9 on Scoutfly

09/26/2010 02:30 PM - Dan Shope

|  |           |                        |            |
|--|-----------|------------------------|------------|
| <b>Status:</b>   | Fixed     | <b>Start date:</b>     | 09/26/2010 |
| <b>Priority:</b>   | Normal    | <b>Due date:</b>       |            |
| <b>Assignee:</b>   | Chris Mar | <b>% Done:</b>         | 0%         |
| <b>Category:</b>   | Scoutfly  | <b>Estimated time:</b> | 0.00 hour  |
| <b>Target version:</b>   | 1.0       |                        |            |
| <b>Description</b>   |           |                        |            |
| currently is 481ohms   |           |                        |            |
| we are sourcing 487ohm parts instead, so update values to reflect this change. |           |                        |            |

### History

---

#1 - 09/26/2010 03:08 PM - Chris Mar

- Status changed from Assigned to Fixed