

Colony Scout - Bug #1440

value change R8 and R9 on Scoutfly

09/26/2010 02:30 PM - Dan Shope

<b>Status:</b>	Fixed	<b>Start date:</b>	09/26/2010
<b>Priority:</b>	Normal	<b>Due date:</b>	
<b>Assignee:</b>	Chris Mar	<b>% Done:</b>	0%
<b>Category:</b>	Scoutfly	<b>Estimated time:</b>	0.00 hour
<b>Target version:</b>	1.0		
<b>Description</b>			
currently is 481ohms			
we are sourcing 487ohm parts instead, so update values to reflect this change.			

History

- #1 - 09/26/2010 03:08 PM - Chris Mar
- Status changed from Assigned to Fixed