

## Colony - Issues

| #   | Tracker | Status     | Priority | Subject   | Assignee      | Updated             | Category              | % Done |
|-----|---------|------------|----------|---|---------------|---------------------|-----------------------|--------|
| 316 | Task    | Fixed      | High     | SURG S09 Application  | Austin Buchan | 03/21/2009 12:47 PM | Administration        | 0      |
| 303 | Bug     | Fixed      | Normal   | Bayboard orb and beacons can't be on at the same time           | Austin Buchan | 03/21/2009 12:48 PM | Autonomous Recharging | 0      |
| 344 | Task    | Worksforme | Normal   | Construct New LED Circuit to Mimic IR LED Current on BOM Boards | Austin Buchan | 04/08/2009 11:40 PM | Diagnostic Station    | 100    |
| 175 | Task    | Fixed      | Normal   | F08 SURG application  | Austin Buchan | 03/21/2009 12:42 PM | Administration        | 0      |
| 341 | Task    | Worksforme | Normal   | Mimic BOM LED Circuit for Diagnostic Station                    | Austin Buchan | 04/08/2009 11:41 PM | Diagnostic Station    | 100    |
| 490 | Task    | Fixed      | Normal   | Spec out new wheels for the robot                               | Austin Buchan | 09/10/2009 04:54 PM | Hardware              | 100    |
| 445 | Task    | Wontfix    | Normal   | Test Orb Driver Code  | Austin Buchan | 09/30/2010 09:05 PM | Library               | 0      |
| 174 | Task    | Fixed      | Low      | BOM 1.5 driver  | Austin Buchan | 03/21/2009 12:50 PM | Library               | 0      |
| 351 | Task    | Wontfix    | Tabled   | Add bayboard and chargeboard status table                       | Austin Buchan | 09/30/2010 07:53 PM | Hardware              | 0      |
| 306 | Bug     | Fixed      | Tabled   | BOM 1.5 Shift register error                                    | Austin Buchan | 03/21/2009 12:50 PM | Library               | 0      |
| 242 | Task    | Fixed      | Tabled   | LCD module  | Austin Buchan | 04/10/2009 05:04 PM | Hardware              | 0      |
| 338 | Task    | Wontfix    | Tabled   | Program Bayboard EEPROM   | Austin Buchan | 09/30/2010 07:54 PM | Autonomous Recharging | 0      |