

Colony - Issues

| # | Tracker | Status | Priority | Subject | Assignee | Updated | Category | % Done |
|-----|---------|------------|----------|---|---------------|---------------------|-----------------------|--------|
| 303 | Bug | Fixed | Normal | Bayboard orb and beacons can't be on at the same time | Austin Buchan | 03/21/2009 12:48 PM | Autonomous Recharging | 0 |
| 174 | Task | Fixed | Low | BOM 1.5 driver | Austin Buchan | 03/21/2009 12:50 PM | Library | 0 |
| 306 | Bug | Fixed | Tabled | BOM 1.5 Shift register error | Austin Buchan | 03/21/2009 12:50 PM | Library | 0 |
| 175 | Task | Fixed | Normal | F08 SURG application | Austin Buchan | 03/21/2009 12:42 PM | Administration | 0 |
| 242 | Task | Fixed | Tabled | LCD module | Austin Buchan | 04/10/2009 05:04 PM | Hardware | 0 |
| 490 | Task | Fixed | Normal | Spec out new wheels for the robot | Austin Buchan | 09/10/2009 04:54 PM | Hardware | 100 |
| 316 | Task | Fixed | High | SURG S09 Application | Austin Buchan | 03/21/2009 12:47 PM | Administration | 0 |
| 351 | Task | Wontfix | Tabled | Add bayboard and chargeboard status table | Austin Buchan | 09/30/2010 07:53 PM | Hardware | 0 |
| 338 | Task | Wontfix | Tabled | Program Bayboard EEPROM | Austin Buchan | 09/30/2010 07:54 PM | Autonomous Recharging | 0 |
| 445 | Task | Wontfix | Normal | Test Orb Driver Code | Austin Buchan | 09/30/2010 09:05 PM | Library | 0 |
| 344 | Task | Worksforme | Normal | Construct New LED Circuit to Mimic IR LED Current on BOM Boards | Austin Buchan | 04/08/2009 11:40 PM | Diagnostic Station | 100 |
| 341 | Task | Worksforme | Normal | Mimic BOM LED Circuit for Diagnostic Station | Austin Buchan | 04/08/2009 11:41 PM | Diagnostic Station | 100 |