Colony Scout - Bug #2169

FL Encoder Ticks Backward

03/31/2013 02:31 PM - Alex Zirbel

Status:	Fixed	**Start date:**	03/31/2013
Priority:	Normal	**Due date:**	
Assignee:	Julian Binder	**% Done:**	0%
Category:	EE Hardware	**Estimated time:**	0.00 hour
Target version:			

Description

Colony software has determined that the front left encoder is backward.

This has been fixed in software, but should be fixed in hardware next time the scout is taken apart.

Lots of wires in there. Don't know how you guys keep them all straight.

History

#1 - 10/29/2013 03:44 PM - Julian Binder

- Status changed from Assigned to Fixed