Colony - Bug #303

Bayboard orb and beacons can't be on at the same time

09/19/2008 05:04 PM - Kevin Woo

Status:	Fixed	**Start date:**	
Priority:	Normal	**Due date:**	
Assignee:	Austin Buchan	**% Done:**	0%
Category:	Autonomous Recharging	**Estimated time:**	0.00 hour
Target version:	Autonomous Recharging		

Description

Figure out why they both can't be on at the same time.

History

#1 - 10/03/2008 04:59 PM - Kevin Woo

- Status changed from New to 5

Fixed.

#3 - 03/21/2009 12:45 PM - Rich Hong

- Status changed from 5 to Fixed

#4 - 03/21/2009 12:48 PM - Rich Hong

- Category set to Autonomous Recharging