# Tooltron - Bug #1197

## Keypad row 3 (7,8,9,C) does not work

03/27/2010 02:47 PM - Brad Neuman

| | | | |
|---|---|---|---|
| **Status:** | Assigned | **Start date:** | 03/27/2010 |
| **Priority:** | Low | **Due date:** | |
| **Assignee:** | | **% Done:** | 0% |
| **Category:** | | **Estimated time:** | 0.00 hour |
| **Target version:** | 2.0 | | |

**Description**

The keypad isn't busted (we probed the leads and saw that rows were connected) but we don't get anything from row 3.

We tried adding delay_ms calls after setting the DDRs in the get button code and that didn't help.

This isn't very critical because these buttons will never be used, but still.

**History**

**#1 - 03/27/2010 08:48 PM - Kevin Woo**

*- Target version set to 2.0*