Colony

		201	1-1	12				20	12-1			2	2012	2-2				2	2012	2-3				201	2-4				2012	-5	
	49	50	D	51	52	2	1	2	3	4	5	6	7	7	8	9	1	0	11	12	2 13	3	14	15	16	17	18	19) 2) 2	!1
Colony									-				-	-				_					Col	ony	•						
Battery Level Indicator																															
Improve library error codes																															
Better sanity check for invalid BOM type																															
XBee/Wireless Initialization																															
get all the library inti's and functions ()																															
Xbee Documentation																															
xbee baud rates																															
Wireless - core send, ack functions																															
Wireless - xbee.c																															
xbee id																															
Conclusion on filter design		sig																													
Figure out rangefinders group		sig																													
Complete SURG form		sig																													
Check/Order robot battery clips	As	sig	ne	d 5	0%																										
Line Follower Collimator																															
Redo robot pants																															
Get Colony videos onto VideoTron. Embed in ()																															
Clean up repository branches																															
Add Line Following to Library																															
Profile different mapping surfaces																															
Make Hunter-Prey Ref More Verbose																															
Clean up Colony-New and prepare for next ()																															
Implement Intersection Behavior																															
wl_basic_do_default(int *length) doesn't ()																															
Schedule Fleet Maintenence Day																															
Discuss and Contact about Extra Colony III ()																															
Colony - Hardware																															

Investigate how to use the JTAG ICE
olony - Library
Make sure all robots program the correct ()