

Colony Scout - Issues

| # | Tracker | Status | Priority | Subject | Assignee | Updated | Category | % Done |
|------|---------|----------|----------|--|-----------------|---------------------|----------|--------|
| 2121 | Bug | Assigned | Normal | File Error Service call | Alex Zirbel | 11/16/2012 06:12 PM | | 0 |
| 2110 | Bug | Assigned | Normal | BOM returns values even when IR LED cannot possibly permeate through the material it is enclosed by. | Thomas Mullins | 11/11/2012 02:56 PM | | 0 |
| 2109 | Bug | Assigned | Normal | Add Fuel Guage and Protection circuit to charge board | Julian Binder | 11/11/2012 03:31 PM | | 0 |
| 1878 | Bug | Assigned | Normal | Cliff Detection | Lalitha Ganesan | 10/26/2011 06:07 PM | OS | 0 |
| 1807 | Bug | Assigned | Normal | Website Work Log | Dan Shope | 10/15/2011 07:12 PM | Website | 80 |
| 1547 | Bug | Assigned | Normal | Fix Encoder pinout on breakfly | Abraham Levkoy | 10/05/2011 05:53 PM | Breakfly | 0 |