

## Issues

| #    | Project      | Tracker     | Status     | Priority | Subject  | Assignee    | Updated             | Category | % Done |
|------|--------------|-------------|------------|----------|--|-------------|---------------------|----------|--------|
| 1355 | Tooltron     | Task        | Assigned   | Normal   | Document new Error codes on Cardbox                          | Kevin Woo   | 05/10/2010 06:24 PM |          | 0      |
| 1341 | Colony Scout | Task        | Fixed      | Normal   | Level shifter for motor control/pwm signals                  | Kevin Woo   | 07/29/2010 07:13 PM | Scoutfly | 0      |
| 1328 | Colony Scout | Task        | Wontfix    | Normal   | Remove extraneous features from Scout                        | Kevin Woo   | 07/29/2010 07:15 PM | Scoutfly | 0      |
| 1327 | Tooltron     | Bug         | Assigned   | Normal   | Server dies when internet is out                             | Brad Neuman | 04/24/2010 06:25 PM |          | 0      |
| 1201 | Tooltron     | Task        | Duplicate  | Normal   | Document the Server  | Brad Neuman | 05/11/2010 07:35 PM |          | 0      |
| 1200 | Tooltron     | Task        | Duplicate  | Normal   | Update state machine interactions between cardbox and server | Kevin Woo   | 04/09/2010 09:22 PM |          | 0      |
| 1199 | Tooltron     | Task        | Assigned   | Normal   | Document the States of the toolbox/cardbox                   | Kevin Woo   | 03/27/2010 08:53 PM |          | 0      |
| 1198 | Tooltron     | Task        | Assigned   | Normal   | Document the Network Bootloader                              | Kevin Woo   | 03/27/2010 08:54 PM |          | 0      |
| 1179 | Tooltron     | Bug         | Fixed      | High     | Tool ACL issues  | Brad Neuman | 03/27/2010 03:36 PM |          | 0      |
| 1150 | Tooltron     | Bug         | Worksforme | Normal   | Fix USB issue with RS485 chip on cardbox schematic/layout    | Kevin Woo   | 03/27/2010 08:47 PM |          | 0      |
| 1145 | Tooltron     | Task        | Fixed      | Normal   | Figure out tool times for each tool                          | Brad Neuman | 03/23/2010 05:59 PM |          | 0      |
| 1144 | Tooltron     | Task        | Fixed      | Normal   | Assign public tool numbers and print the list                | Brad Neuman | 03/23/2010 06:00 PM |          | 0      |
| 1143 | Tooltron     | Task        | Fixed      | Normal   | Mount cardbox  |             | 03/04/2010 11:45 PM |          | 0      |
| 1142 | Tooltron     | Task        | Worksforme | Normal   | Hot glue connectors in the two bandsaws                      | Kevin Woo   | 03/27/2010 08:52 PM |          | 50     |
| 1141 | Tooltron     | Task        | Fixed      | Normal   | Test Network programming with multiple tools                 | Brad Neuman | 03/04/2010 11:45 PM |          | 0      |
| 1140 | Tooltron     | Enhancement | Fixed      | Normal   | Tool ping packet   | Kevin Woo   | 03/03/2010 08:39 PM |          | 0      |
| 1139 | Tooltron     | Task        | Fixed      | Normal   | Program correct tool IDs into the eeprom on all tools        | Brad Neuman | 03/04/2010 11:46 PM |          | 0      |
| 1138 | Tooltron     | Task        | Fixed      | Normal   | Reprogram all tools with new fuses/bootloader                | Brad Neuman | 03/04/2010 11:46 PM |          | 0      |
| 1137 | Tooltron     | Task        | Fixed      | Normal   | Modify rs482 connector for cardbox                           | Kevin Woo   | 03/04/2010 11:47 PM |          | 0      |
| 1133 | Tooltron     | Bug         | Fixed      | Normal   | Tool and server take wrong turnon message                    | Brad Neuman | 03/01/2010 02:41 AM |          | 0      |
| 1132 | Tooltron     | Enhancement | Wontfix    | Normal   | Add a FUSE section to the bootloader                         | Kevin Woo   | 02/24/2010 06:22 PM |          | 0      |
| 1131 | Tooltron     | Bug         | Fixed      | Normal   | network programming script sends 1 too many packets          | Brad Neuman | 02/28/2010 03:31 PM |          | 0      |
| 1130 | Tooltron     | Bug         | Fixed      | Normal   | add compiler directive to prevent stack junk                 | Kevin Woo   | 02/24/2010 05:53 PM |          | 0      |
| 1128 | Tooltron     | Enhancement | Fixed      | Normal   | Reorganize repository to share common code                   | Kevin Woo   | 02/24/2010 01:14 AM |          | 0      |
| 1126 | Tooltron     | Task        | Fixed      | Normal   | Test new cardbox board                                       | Kevin Woo   | 03/04/2010 12:46 AM |          | 0      |
| 1125 | Tooltron     | Task        | Fixed      | Normal   | Cut usb cable to make new cardbox cable                      | Kevin Woo   | 02/27/2010 02:25 PM |          | 0      |
| 1124 | Tooltron     | Task        | Fixed      | Normal   | Jump table for user code                                     | Kevin Woo   | 02/28/2010 05:00 PM |          | 0      |
| 1123 | Tooltron     | Task        | Fixed      | Normal   | clear user code jump when programming                        | Kevin Woo   | 02/23/2010 09:57 PM |          | 0      |
| 1122 | Tooltron     | Task        | Fixed      | Normal   | Send nacks   | Kevin Woo   | 02/23/2010 09:58 PM |          | 0      |
| 1120 | Tooltron     | Task        | Fixed      | Normal   | Packet handler timeouts                                      | Kevin Woo   | 02/23/2010 09:29 PM |          | 0      |

| #    | Project      | Tracker     | Status  | Priority | Subject   | Assignee     | Updated             | Category   | % Done |
|------|--------------|-------------|---------|----------|---|--------------|---------------------|------------|--------|
| 1119 | Tooltron     | Task        | Fixed   | Normal   | Watchdog Reset  | Kevin Woo    | 02/23/2010 11:14 PM |            | 100    |
| 1104 | Tooltron     | Bug         | Fixed   | Normal   | Remove magic number from uart init                          | Kevin Woo    | 03/01/2010 02:40 AM |            | 0      |
| 1103 | Tooltron     | Bug         | Fixed   | Normal   | Tools send wrong Ack message                                | Kevin Woo    | 03/01/2010 02:42 AM |            | 0      |
| 1102 | Colony Scout | Task        | Fixed   | Normal   | Make JST 2,3,4 pin connector footprints                     | Kevin Woo    | 02/10/2010 04:16 PM | Scoutfly   | 0      |
| 1101 | Colony Scout | Bug         | Fixed   | Normal   | Add JST connectors to the bottom side for the front sensors | Kevin Woo    | 02/22/2010 02:39 PM | Scoutfly   | 0      |
| 1100 | Colony Scout | Task        | Fixed   | Normal   | Spec 2, 3 and 4 pin JST ZH connectors                       | Kevin Woo    | 02/10/2010 03:21 PM | Scoutfly   | 0      |
| 1099 | Colony Scout | Bug         | Fixed   | Normal   | Remove Extra FFC  | Kevin Woo    | 02/22/2010 02:47 PM | Scoutfly   | 0      |
| 1093 | Colony Scout | Bug         | Fixed   | Normal   | Stepper controller should be powered by VCC                 | Kevin Woo    | 02/22/2010 02:51 PM | Scoutfly   | 0      |
| 1090 | Tooltron     | Task        | Wontfix | Normal   | Buy OR gates  | Kevin Woo    | 02/23/2010 08:37 PM |            | 0      |
| 1089 | Tooltron     | Enhancement | Fixed   | Normal   | New Cardbox Board   | Kevin Woo    | 02/23/2010 08:37 PM |            | 0      |
| 1088 | Colony Scout | Bug         | Invalid | Normal   | Switch motor power from VCC to VBatt                        | Kevin Woo    | 07/29/2010 07:15 PM | Scoutfly   | 0      |
| 1087 | Colony Scout | Task        | Fixed   | Normal   | Design Breakfly   | Rohan Aletty | 10/04/2010 03:10 AM | Breakfly   | 90     |
| 1086 | Colony Scout | Task        | Invalid | Normal   | Design debug board  | Emily Hart   | 07/29/2010 07:19 PM | Scoutfly   | 0      |
| 1085 | Colony Scout | Task        | Fixed   | Normal   | Get the BreakFly Dimensions and positioning                 | Dan Shope    | 02/09/2010 06:52 PM | Mechanical | 0      |
| 1079 | Tooltron     | Enhancement | Fixed   | Normal   | Network Programming Support                                 | Brad Neuman  | 02/27/2010 02:25 PM |            | 0      |
| 1046 | Colony Scout | Task        | Fixed   | Low      | Update BOM  | Kevin Woo    | 02/06/2010 09:15 PM | Scoutfly   | 0      |
| 1045 | Colony Scout | Task        | Fixed   | Normal   | Add a USB A port to the board on the host controller        | Kevin Woo    | 02/05/2010 11:11 PM | Scoutfly   | 0      |
| 1044 | Colony Scout | Bug         | Fixed   | Normal   | Choose a new rtc backup battery                             | Kevin Woo    | 02/06/2010 09:04 PM | Scoutfly   | 0      |
| 1039 | Colony Scout | Bug         | Fixed   | Normal   | Tie oscsel to the RTC Battery                               | Kevin Woo    | 02/22/2010 02:52 PM | Scoutfly   | 0      |
| 1038 | Colony Scout | Task        | Fixed   | Normal   | Modify Power supply   | Kevin Woo    | 01/22/2010 08:24 PM | Scoutfly   | 0      |
| 1037 | Colony Scout | Task        | Fixed   | Normal   | Put 50MHz oscillator on the ethernet phy chip               | Kevin Woo    | 02/05/2010 11:16 PM | Scoutfly   | 0      |
| 1036 | Colony Scout | Task        | Invalid | Normal   | Doublecheck SDRAM footprint                                 | Kevin Woo    | 01/26/2010 11:28 PM | Scoutfly   | 0      |
| 1035 | Colony Scout | Bug         | Fixed   | Normal   | Redo decoupling caps on ARM                                 | Kevin Woo    | 01/22/2010 05:20 PM | Scoutfly   | 0      |
| 1032 | Colony Scout | Bug         | Fixed   | Normal   | Part Change   | Kevin Woo    | 02/05/2010 11:21 PM | Scoutfly   | 0      |
| 1023 | Colony Scout | Task        | Fixed   | Normal   | Double check ARM Analog VDD supply voltage                  | Kevin Woo    | 01/19/2010 02:31 PM | Scoutfly   | 0      |
| 1022 | Colony Scout | Bug         | Fixed   | Normal   | Replace hex schmitt triggers with duals                     | Kevin Woo    | 01/19/2010 02:28 PM | Scoutfly   | 0      |
| 1021 | Colony Scout | Bug         | Fixed   | Normal   | I2C Level shifter on the AVR I2C lines                      | Kevin Woo    | 01/19/2010 02:16 PM | Scoutfly   | 0      |
| 1018 | Colony Scout | Task        | Fixed   | Normal   | Test motor backdrive  | Kevin Woo    | 07/29/2010 07:18 PM | Scoutfly   | 0      |
| 1017 | Colony Scout | Enhancement | Wontfix | Normal   | Separate grounds  | Kevin Woo    | 07/29/2010 07:12 PM | Scoutfly   | 0      |
| 1016 | Colony Scout | Enhancement | Wontfix | Normal   | ESD Protection  | Kevin Woo    | 07/29/2010 07:14 PM | Scoutfly   | 0      |
| 1015 | Colony Scout | Enhancement | Fixed   | Normal   | Resnets for LED arrays                                      | Kevin Woo    | 01/16/2010 02:47 PM | Scoutfly   | 0      |
| 1013 | Colony Scout | Bug         | Fixed   | Normal   | Circuit simulate LEDs                                       | Kevin Woo    | 01/16/2010 12:22 AM | Scoutfly   | 0      |

| #    | Project      | Tracker     | Status     | Priority | Subject   | Assignee        | Updated             | Category  | % Done |
|------|--------------|-------------|------------|----------|---|-----------------|---------------------|-----------|--------|
| 1005 | Colony Scout | Bug         | Fixed      | Normal   | Move pushbutton to ffc  | Kevin Woo       | 01/15/2010 04:58 PM | Scoutfly  | 0      |
| 1004 | Colony Scout | Bug         | Fixed      | Normal   | Split power into input and output connectors                  | Kevin Woo       | 01/15/2010 04:55 PM | Scoutfly  | 0      |
| 1003 | Colony Scout | Enhancement | Fixed      | Normal   | Replace giant DPAK BJTs with a smaller one                    | Kevin Woo       | 01/15/2010 04:35 PM | Scoutfly  | 0      |
| 985  | Colony Scout | Bug         | Fixed      | Normal   | Add RX/TX UART pin bypass to the AVR for debugging            | Kevin Woo       | 01/13/2010 08:22 PM | Scoutfly  | 0      |
| 984  | Colony Scout | Bug         | Fixed      | Normal   | Add ffc connectors to the board to replace cgrids             | Kevin Woo       | 01/14/2010 02:42 AM | Scoutfly  | 0      |
| 983  | Colony Scout | Bug         | Fixed      | Normal   | Add micro a/b usb-otg connector                               | Kevin Woo       | 01/15/2010 10:00 PM | Scoutfly  | 0      |
| 982  | Colony Scout | Bug         | Fixed      | Normal   | Add UART for the BOM  | Kevin Woo       | 01/13/2010 08:24 PM | Scoutfly  | 0      |
| 981  | Colony Scout | Bug         | Fixed      | Normal   | Modify accessory ports  | Kevin Woo       | 01/13/2010 08:25 PM | Scoutfly  | 0      |
| 973  | Colony Scout | Task        | Fixed      | Normal   | Share schematic + board on dropbox with dan                   | Kevin Woo       | 01/12/2010 05:34 AM | Scoutfly  | 0      |
| 972  | Colony Scout | Enhancement | Fixed      | Normal   | Replace RF chip crystal with smaller oscillator               | Kevin Woo       | 01/12/2010 09:34 PM | Scoutfly  | 0      |
| 971  | Colony Scout | Enhancement | Fixed      | Normal   | Remove led bar and use individual LEDs instead                |                 | 01/11/2010 08:32 PM |           | 0      |
| 970  | Colony Scout | Task        | Fixed      | Normal   | Find all resistors we need                                    | Kevin Woo       | 02/06/2010 09:05 PM | Scoutfly  | 0      |
| 969  | Colony Scout | Task        | Fixed      | Normal   | Look for smaller ethernet connector                           | Kevin Woo       | 01/15/2010 10:55 PM | Scoutfly  | 0      |
| 968  | Colony Scout | Task        | Fixed      | Normal   | Double-check Resistor Divider Values                          | Kevin Woo       | 01/13/2010 08:15 PM | Scoutfly  | 0      |
| 967  | Colony Scout | Task        | Fixed      | Normal   | Double-check IC Footprints                                    | Kevin Woo       | 01/13/2010 12:24 AM | Scoutfly  | 0      |
| 693  | Colony       | Bug         | Assigned   | Tabled   | Better sanity check for invalid BOM type                      | John Sexton     | 10/01/2010 05:45 PM | Hardware  | 0      |
| 617  | Tooltron     | Task        | Invalid    | Normal   | Buy Conduit   | Jimmy Bourne    | 03/27/2010 08:52 PM |           | 50     |
| 506  | Tooltron     | Task        | Fixed      | Normal   | Mount Tooltron Boards   | Paul Desiderio  | 03/05/2010 01:28 AM |           | 0      |
| 503  | Tooltron     | Enhancement | Fixed      | Normal   | Tool usage logging  | Brad Neuman     | 01/18/2010 06:45 PM |           | 0      |
| 491  | Colony       | Bug         | Worksforme | Normal   | ADC ref voltage issue with range finders                      | Chris Mar       | 10/01/2010 07:45 PM | Hardware  | 100    |
| 490  | Colony       | Task        | Fixed      | Normal   | Spec out new wheels for the robot                             | Austin Buchan   | 09/10/2009 04:54 PM | Hardware  | 100    |
| 446  | Colony       | Task        | Wontfix    | Normal   | Implement the BOM in the Simulator                            | Brad Neuman     | 09/30/2010 08:17 PM | Simulator | 0      |
| 445  | Colony       | Task        | Wontfix    | Normal   | Test Orb Driver Code  | Austin Buchan   | 09/30/2010 09:05 PM | Library   | 0      |
| 391  | Colony       | Task        | Wontfix    | Normal   | Investigate and profile the avr-libc floating point emulation | Brad Neuman     | 09/25/2010 03:18 PM | Library   | 0      |
| 390  | Colony       | Task        | Feedback   | Tabled   | Investigate how to use the JTAG ICE                           | Nico Paris      | 09/24/2009 11:08 AM | Hardware  | 0      |
| 388  | Colony       | Enhancement | Wontfix    | Low      | Make RTC more granular and adjustable                         | Martin Herrmann | 09/25/2010 03:09 PM | Library   | 0      |
| 387  | Colony       | Task        | Fixed      | Normal   | Talk to Aaron about the JTAG ICE and how to use               | Kevin Woo       | 04/03/2009 10:01 AM | Hardware  | 0      |
| 368  | Colony       | Task        | Assigned   | Tabled   | Make sure all robots program the correct xbee id from eeprom  | Brian Coltin    | 10/02/2010 07:24 PM | Library   | 0      |
| 367  | Colony       | Enhancement | Fixed      | Normal   | Prevent loading of non robot code into the simulator          | Brad Neuman     | 04/10/2009 05:13 PM | Simulator | 0      |
| 354  | Colony       | Task        | Fixed      | Low      | Clean up presentations and papers                             | Kevin Woo       | 09/24/2010 01:53 PM |           | 0      |
| 353  | Colony       | Task        | Fixed      | Normal   | Make Doxygen Tutorial/Presentation                            | Alex Zirbel     | 12/14/2011 05:27 PM |           | 0      |

| #   | Project | Tracker     | Status     | Priority | Subject   | Assignee        | Updated             | Category              | % Done |
|-----|---------|-------------|------------|----------|---|-----------------|---------------------|-----------------------|--------|
| 352 | Colony  | Task        | Wontfix    | Normal   | Research alternatives for xbee dongles                                | James Kong      | 09/09/2009 10:30 PM | Hardware              | 0      |
| 351 | Colony  | Task        | Wontfix    | Tabled   | Add bayboard and chargeboard status table                             | Austin Buchan   | 09/30/2010 07:53 PM | Hardware              | 0      |
| 340 | Colony  | Enhancement | Fixed      | Tabled   | Respin the XBee Dongles   | Nico Paris      | 09/30/2010 07:52 PM | Hardware              | 0      |
| 339 | Colony  | Task        | Fixed      | Normal   | Clean up memory for multiple robots in simulator                      | Brad Neuman     | 04/03/2009 05:09 PM | Simulator             | 0      |
| 338 | Colony  | Task        | Wontfix    | Tabled   | Program Bayboard EEPROM   | Austin Buchan   | 09/30/2010 07:54 PM | Autonomous Recharging | 0      |
| 337 | Colony  | Task        | Wontfix    | High     | Update Wireless Maximum Number of XBees                               | Brian Coltin    | 10/02/2010 07:11 PM | Library               | 0      |
| 336 | Colony  | Task        | Fixed      | Low      | Port Old Public Colony Page   | Kevin Woo       | 03/21/2009 12:50 PM |                       | 0      |
| 335 | Colony  | Task        | Fixed      | Low      | Testing new encoder mounts  | Ben Poole       | 03/21/2009 12:49 PM | Hardware              | 0      |
| 330 | Colony  | Task        | Invalid    | Tabled   | Investigate the Use of TI Zigbee Chip for Next Revision               |                 | 09/30/2010 07:46 PM | Hardware              | 0      |
| 323 | Colony  | Enhancement | Fixed      | Tabled   | Wireless bootloading  | Ryan Cahoon     | 09/26/2009 04:54 AM |                       | 90     |
| 322 | Colony  | Task        | Fixed      | High     | Depsit SURG Checks  | James Kong      | 03/21/2009 12:47 PM | Administration        | 0      |
| 321 | Colony  | Task        | Fixed      | Low      | Talk to Austria Micro about Encoder Magnet Misalignment Issues        | Chris Mar       | 03/21/2009 12:49 PM | Hardware              | 0      |
| 320 | Colony  | Enhancement | New        | Tabled   | Automatically update robot status page with testing station           |                 | 03/21/2009 12:55 PM | Diagnostic Station    | 0      |
| 319 | Colony  | Task        | Wontfix    | High     | Talk to Priya About Xbee Dongles                                      | James Kong      | 03/21/2009 12:49 PM | Hardware              | 0      |
| 318 | Colony  | Task        | Fixed      | High     | Testing colony trac ticket emails                                     | Kevin Woo       | 03/21/2009 12:47 PM | Administration        | 0      |
| 317 | Colony  | Task        | Fixed      | Low      | Find AVR presentation   | Kevin Woo       | 03/21/2009 12:50 PM |                       | 0      |
| 316 | Colony  | Task        | Fixed      | High     | SURG S09 Application  | Austin Buchan   | 03/21/2009 12:47 PM | Administration        | 0      |
| 315 | Colony  | Enhancement | Wontfix    | Low      | Joystick control cleanup  | Bradley Yoo     | 03/21/2009 12:50 PM | Library               | 0      |
| 314 | Colony  | Task        | Worksforme | High     | Send Charging Board Documents to Kevin                                | Brad Neuman     | 03/21/2009 12:48 PM | Autonomous Recharging | 0      |
| 313 | Colony  | Task        | Fixed      | Low      | Move wiki to trac   | Kevin Woo       | 03/21/2009 12:47 PM | Administration        | 0      |
| 312 | Colony  | Task        | Fixed      | High     | Make the wireless presentation  | Brian Coltin    | 03/21/2009 12:50 PM |                       | 0      |
| 311 | Colony  | Enhancement | Fixed      | Normal   | Homing beacon sensor mount  | Jimmy Bourne    | 03/21/2009 12:49 PM | Hardware              | 0      |
| 310 | Colony  | Task        | Fixed      | Normal   | Fix milestones and categories for trac                                | Kevin Woo       | 03/21/2009 12:47 PM | Administration        | 0      |
| 309 | Colony  | Enhancement | Fixed      | High     | Make 1 source for library files                                       | Brian Coltin    | 03/21/2009 12:50 PM | Library               | 0      |
| 308 | Colony  | Task        | Wontfix    | High     | Wireless - merge the bayboard and dragonfly versions                  | Brian Coltin    | 09/30/2010 08:36 PM | Library               | 0      |
| 307 | Colony  | Task        | Fixed      | Low      | Merge encoders into the trunk   | Justin Scheiner | 03/21/2009 12:50 PM | Library               | 0      |
| 306 | Colony  | Bug         | Fixed      | Tabled   | BOM 1.5 Shift register error  | Austin Buchan   | 03/21/2009 12:50 PM | Library               | 0      |
| 305 | Colony  | Bug         | Wontfix    | Normal   | Wireless - number of robots in token ring doesn't report right number | Brian Coltin    | 09/24/2010 01:51 PM | Library               | 0      |

| #   | Project | Tracker     | Status     | Priority | Subject   | Assignee        | Updated             | Category              | % Done |
|-----|---------|-------------|------------|----------|---|-----------------|---------------------|-----------------------|--------|
| 304 | Colony  | Enhancement | Invalid    | Low      | Rangefinders code distance comments                   | Brad Neuman     | 03/21/2009 12:50 PM | Library               | 0      |
| 303 | Colony  | Bug         | Fixed      | Normal   | Bayboard orb and beacons can't be on at the same time | Austin Buchan   | 03/21/2009 12:48 PM | Autonomous Recharging | 0      |
| 302 | Colony  | Enhancement | Fixed      | Low      | Encoders documentation                                | Justin Scheiner | 03/21/2009 12:50 PM | Library               | 0      |
| 301 | Colony  | Task        | Fixed      | Low      | Fix analog8.c doxygen comments                        | Kevin Woo       | 03/21/2009 12:50 PM | Library               | 0      |
| 298 | Colony  | Task        | Wontfix    | Low      | Copy old repository to roboclub8                      | Kevin Woo       | 03/21/2009 12:47 PM | Administration        | 0      |
| 295 | Colony  | Task        | Fixed      | High     | Set up email notification on trac                     | Kevin Woo       | 03/21/2009 12:47 PM | Administration        | 0      |
| 274 | Colony  | Task        | Fixed      | Low      | Unit Test Architecture                                | Brad Neuman     | 03/21/2009 12:51 PM |                       | 0      |
| 264 | Colony  | Task        | Worksforme | High     | Thought Paper   | James Kong      | 03/21/2009 12:47 PM | Administration        | 0      |
| 241 | Colony  | Enhancement | Fixed      | Low      | Video From ColoNet GUI                                | Greg Tress      | 03/21/2009 12:48 PM | Autonomous Recharging | 0      |
| 240 | Colony  | Task        | Fixed      | Tabled   | delay_ms rewrite                                      | Kevin Woo       | 03/21/2009 12:50 PM | Library               | 0      |
| 239 | Colony  | Task        | Fixed      | Tabled   | Port Old Meeting Minutes Over                         | James Kong      | 03/21/2009 12:47 PM | Administration        | 0      |
| 237 | Colony  | Enhancement | Feedback   | Tabled   | Design Dragonfly Replacement Board                    |                 | 03/21/2009 12:54 PM | Hardware              | 0      |
| 230 | Colony  | Enhancement | Worksforme | Normal   | More Friendly Makefile for Library Work               | Brian Coltin    | 03/21/2009 12:50 PM | Library               | 0      |
| 214 | Colony  | Enhancement | Fixed      | Normal   | Wrapper functions for backwards compatability on BOM  | Chris Mar       | 03/21/2009 12:50 PM | Library               | 0      |
| 203 | Colony  | Enhancement | Wontfix    | Low      | I2C Multimaster for USI port                          | Kevin Woo       | 03/21/2009 12:50 PM | Library               | 0      |
| 202 | Colony  | Bug         | Invalid    | High     | Analog Port   | Kevin Woo       | 03/21/2009 12:50 PM | Library               | 0      |
| 201 | Colony  | Task        | Invalid    | Normal   | High Intensity Light Prototype                        | Terrence Copney | 03/21/2009 12:50 PM |                       | 0      |
| 200 | Colony  | Task        | Wontfix    | Normal   | Protpe Tricolor Object ID                             | Andrew Yeager   | 03/21/2009 12:50 PM |                       | 0      |
| 199 | Colony  | Task        | Wontfix    | Low      | Research RFID   | Victor Marmol   | 03/21/2009 12:50 PM |                       | 0      |
| 183 | Colony  | Task        | Fixed      | Normal   | Write Encoder Library                                 | Brad Neuman     | 03/21/2009 12:49 PM | Hardware              | 0      |