

Issues

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Category	% Done
2109	Colony Scout	Bug	Assigned	Normal	Add Fuel Guage and Protection circuit to charge board	Julian Binder	11/11/2012 03:31 PM		0
2110	Colony Scout	Bug	Assigned	Normal	BOM returns values even when IR LED cannot possibly permeate through the material it is enclosed by.	Thomas Mullins	11/11/2012 02:56 PM		0
2034	Colony	Bug	Wontfix	Normal	Move Stuff From Place to Other Place	Jeff Cooper	09/25/2012 04:38 PM		100
1993	Colony Scout	Task	Fixed	Normal	Design Forklift in Solidworks	Yuyang Guo	09/18/2012 02:00 PM		100