

Colony Scout - Bug #1035

Redo decoupling caps on ARM

01/22/2010 02:38 AM - Kevin Woo

Status:	Fixed	Start date:	01/22/2010
Priority:	Normal	Due date:	
Assignee:	Kevin Woo	% Done:	0%
Category:	Scoutfly	Estimated time:	0.00 hour
Target version:	Development		
Description			

History

#1 - 01/22/2010 05:20 PM - Kevin Woo

- Status changed from Assigned to Fixed