

Tooltron - Bug #1131

network programming script sends 1 too many packets

02/23/2010 11:09 PM - Kevin Woo

Status:	Fixed	Start date:	02/23/2010
Priority:	Normal	Due date:	
Assignee:	Brad Neuman	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:			

Description

When the packet size is exactly divisible by 32 the script sends an extra packet with 32 blank bytes and fails due to not receiving an ack. The board however operates correctly in this case and the program is loaded.

Use case in /programmer/test/main.c with r175

The program size is 222 bytes but the scripts reports it as 224 bytes with .data I believe.

History

#1 - 02/28/2010 03:31 PM - Brad Neuman

- Status changed from Assigned to Fixed