

Tooltron - Bug #1150

Fix USB issue with RS485 chip on cardbox schematic/layout

03/03/2010 02:44 PM - Kevin Woo

Status:	Worksforme	Start date:	03/03/2010
Priority:	Normal	Due date:	
Assignee:	Kevin Woo	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:			
Description			
Can't tie !RE/TE together, need to do TXEN -> TE and !RE -> GND			

History

#1 - 03/27/2010 08:47 PM - Kevin Woo

- Status changed from Assigned to Worksforme