

## Tooltron - Task #1361

### order more boards and replace drill-press 1

05/12/2010 05:29 PM - Brad Neuman

<b>Status:</b> Assigned	<b>Start date:</b> 05/12/2010
<b>Priority:</b> Normal	<b>Due date:</b>
<b>Assignee:</b> Nico Paris	<b>% Done:</b> 0%
<b>Category:</b>	<b>Estimated time:</b> 0.00 hour
<b>Target version:</b> 1.1	
<b>Description</b> Drill press 1 seems like it has a weak board. It is the board which had those random eeprom bit flips and just now it had the code randomly break, although reprogramming fixed it.  I think we should replace that board and we also need some for backups	