

Tooltron - Task #1361

order more boards and replace drill-press 1

05/12/2010 05:29 PM - Brad Neuman

Status:	Assigned	Start date:	05/12/2010
Priority:	Normal	Due date:	
Assignee:	Nico Paris	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:	1.1		
Description			
Drill press 1 seems like it has a weak board. It is the board which had those random eeprom bit flips and just now it had the code randomly break, although reprogramming fixed it.			
I think we should replace that board and we also need some for backups			