

Colony Scout - Bug #1440

value change R8 and R9 on Scoutfly

09/26/2010 02:30 PM - Dan Shope

Status:	Fixed	Start date:	09/26/2010
Priority:	Normal	Due date:	
Assignee:	Chris Mar	% Done:	0%
Category:	Scoutfly	Estimated time:	0.00 hour
Target version:	1.0		
Description			
currently is 481ohms			
we are sourcing 487ohm parts instead, so update values to reflect this change.			

History

#1 - 09/26/2010 03:08 PM - Chris Mar

- Status changed from Assigned to Fixed