

## Colony Scout - Bug #1442

### Scoutfly - Add Grounded Screw Holes

09/26/2010 03:12 PM - Chris Mar

|   |           |                        |            |
|---|-----------|------------------------|------------|
| <b>Status:</b>                              | Fixed     | <b>Start date:</b>     | 09/26/2010 |
| <b>Priority:</b>                            | Normal    | <b>Due date:</b>       |            |
| <b>Assignee:</b>                            | Chris Mar | <b>% Done:</b>         | 50%        |
| <b>Category:</b>                            | Scoutfly  | <b>Estimated time:</b> | 0.00 hour  |
| <b>Target version:</b>                      | 1.0       |                        |            |
| <b>Description</b>                          |           |                        |            |
| Add vias connected to ground                |           |                        |            |
| - .116 drill hole                           |           |                        |            |
| - .179 pad diameter                         |           |                        |            |
| - .250 diameter clearance for ring terminal |           |                        |            |
| Add silk "GND" for front holes              |           |                        |            |

#### History

**#1 - 09/26/2010 03:12 PM - Chris Mar**

- % Done changed from 0 to 50

**#2 - 09/26/2010 03:52 PM - Chris Mar**

Coordinates:

(150, 3350) (4350,3350)

(150,150) (4350,150)

**#3 - 10/01/2010 03:50 PM - Dan Shope**

- Status changed from Assigned to Fixed