

Colony Scout - Bug #1442

Scoutfly - Add Grounded Screw Holes

09/26/2010 03:12 PM - Chris Mar

Status:	Fixed	Start date:	09/26/2010
Priority:	Normal	Due date:	
Assignee:	Chris Mar	% Done:	50%
Category:	Scoutfly	Estimated time:	0.00 hour
Target version:	1.0		
Description			
Add vias connected to ground			
- .116 drill hole			
- .179 pad diameter			
- .250 diameter clearance for ring terminal			
Add silk "GND" for front holes			

History

#1 - 09/26/2010 03:12 PM - Chris Mar

- % Done changed from 0 to 50

#2 - 09/26/2010 03:52 PM - Chris Mar

Coordinates:

(150, 3350) (4350,3350)

(150,150) (4350,150)

#3 - 10/01/2010 03:50 PM - Dan Shope

- Status changed from Assigned to Fixed