

Colony Scout - Bug #1547

Fix Encoder pinout on breakfly

11/01/2010 04:18 PM - Dan Shope

Status:	Assigned	Start date:	11/01/2010
Priority:	Normal	Due date:	
Assignee:	Abraham Levkoy	% Done:	0%
Category:	Breakfly	Estimated time:	0.00 hour
Target version:	1.0		
Description			
Breakfly encoders 2 & 3 have completely different pinouts. These should be changed to match or at least be mirror images - will require board re-routing			

History

#1 - 10/05/2011 05:53 PM - Dan Shope

- Assignee changed from Dan Shope to Abraham Levkoy