

## Colony Scout - Bug #1547

### Fix Encoder pinout on breakfly

11/01/2010 04:18 PM - Dan Shope

<b>Status:</b>	Assigned	<b>Start date:</b>	11/01/2010
<b>Priority:</b>	Normal	<b>Due date:</b>	
<b>Assignee:</b>	Abraham Levkoy	<b>% Done:</b>	0%
<b>Category:</b>	Breakfly	<b>Estimated time:</b>	0.00 hour
<b>Target version:</b>	1.0		
<b>Description</b>			
Breakfly encoders 2 & 3 have completely different pinouts. These should be changed to match or at least be mirror images - will require board re-routing			

#### History

#1 - 10/05/2011 05:53 PM - Dan Shope

- Assignee changed from Dan Shope to Abraham Levkoy