

Colony Scout - Bug #2110

BOM returns values even when IR LED cannot possibly permeate through the material it is enclosed by.

11/11/2012 02:56 PM - Julian Binder

Status:	Assigned	Start date:	11/11/2012
Priority:	Normal	Due date:	
Assignee:	Thomas Mullins	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:			
Description			
Tested by covering with hand and by enclosing in ESD bag. Checked with camera to make sure IR LED was not visible.			