

Colony - Bug #624

Flaky Left Encoder on Bot 14

09/21/2009 07:10 PM - John Sexton

Status: Fixed	Start date: 09/21/2009
Priority: Normal	Due date:
Assignee: Jimmy Bourne	% Done: 0%
Category:	Estimated time: 0.00 hour
Target version:	
Description Bot 14 keeps retuning 1025 on Rich's encoder unit test. Rich says this is because the magnet is getting to close to the encoder chip.	

History

#1 - 10/07/2009 07:41 PM - Jimmy Bourne

- Status changed from Assigned to Fixed