

Colony - Issues

| # | Tracker | Status | Priority | Subject | Assignee | Updated | Category | % Done |
|-----|-------------|---------|----------|--|---------------|---------------------|-----------------------|--------|
| 797 | Bug | Wontfix | Tabled | rename motor.h | Alex Zirbel | 11/09/2011 12:15 AM | Library | 0 |
| 579 | Enhancement | Wontfix | Low | better naming for BOM numbers | | 09/30/2010 07:36 PM | | 0 |
| 578 | Enhancement | Wontfix | Tabled | usb_put* function with fixed width | Ben Wasserman | 10/01/2010 05:28 PM | Library | 0 |
| 576 | Enhancement | Wontfix | Low | BOM calibration | Brad Neuman | 09/25/2010 03:11 PM | | 0 |
| 569 | Task | Invalid | Normal | comment eeprom.c | Brad Neuman | 09/30/2010 08:24 PM | Library | 0 |
| 560 | Bug | Fixed | High | BOM and rangefinder donot work together | James Kong | 09/09/2009 10:32 PM | Library | 0 |
| 447 | Enhancement | Wontfix | Low | add debugging support in simulator | Brian Coltin | 09/25/2010 03:11 PM | Simulator | 0 |
| 365 | Bug | Fixed | Normal | Fix race condition in simulator | Brian Coltin | 03/26/2009 01:54 PM | Simulator | 0 |
| 297 | Task | Fixed | Normal | Rewire encoders | Jimmy Bourne | 03/21/2009 12:49 PM | Hardware | 0 |
| 271 | Task | Wontfix | Low | design wireless packet for use with manipulation | Brad Neuman | 03/21/2009 12:50 PM | | 0 |
| 270 | Enhancement | Wontfix | Low | adapt orbit and BFS for cooperative manipulation | Brad Neuman | 03/21/2009 12:50 PM | | 0 |
| 231 | Bug | Fixed | Low | Resolve ARCHS inductor problem | Brad Neuman | 03/21/2009 12:48 PM | Autonomous Recharging | 0 |
| 196 | Bug | Invalid | High | I2C hangs on ARCHS board | Kevin Woo | 03/21/2009 12:50 PM | | 0 |