

## Colony - Issues

| #   | Tracker     | Status  | Priority | Subject  | Assignee      | Updated             | Category              | % Done |
|-----|-------------|---------|----------|--|---------------|---------------------|-----------------------|--------|
| 797 | Bug         | Wontfix | Tabled   | rename motor.h                                   | Alex Zirbel   | 11/09/2011 12:15 AM | Library               | 0      |
| 578 | Enhancement | Wontfix | Tabled   | usb_put* function with fixed width               | Ben Wasserman | 10/01/2010 05:28 PM | Library               | 0      |
| 569 | Task        | Invalid | Normal   | comment eeprom.c                                 | Brad Neuman   | 09/30/2010 08:24 PM | Library               | 0      |
| 579 | Enhancement | Wontfix | Low      | better naming for BOM numbers                    |               | 09/30/2010 07:36 PM |                       | 0      |
| 576 | Enhancement | Wontfix | Low      | BOM calibration                                  | Brad Neuman   | 09/25/2010 03:11 PM |                       | 0      |
| 447 | Enhancement | Wontfix | Low      | add debugging support in simulator               | Brian Coltin  | 09/25/2010 03:11 PM | Simulator             | 0      |
| 560 | Bug         | Fixed   | High     | BOM and rangefinder donot work together          | James Kong    | 09/09/2009 10:32 PM | Library               | 0      |
| 365 | Bug         | Fixed   | Normal   | Fix race condition in simulator                  | Brian Coltin  | 03/26/2009 01:54 PM | Simulator             | 0      |
| 271 | Task        | Wontfix | Low      | design wireless packet for use with manipulation | Brad Neuman   | 03/21/2009 12:50 PM |                       | 0      |
| 270 | Enhancement | Wontfix | Low      | adapt orbit and BFS for cooperative manipulation | Brad Neuman   | 03/21/2009 12:50 PM |                       | 0      |
| 196 | Bug         | Invalid | High     | I2C hangs on ARCHS board                         | Kevin Woo     | 03/21/2009 12:50 PM |                       | 0      |
| 297 | Task        | Fixed   | Normal   | Rewire encoders                                  | Jimmy Bourne  | 03/21/2009 12:49 PM | Hardware              | 0      |
| 231 | Bug         | Fixed   | Low      | Resolve ARCHS inductor problem                   | Brad Neuman   | 03/21/2009 12:48 PM | Autonomous Recharging | 0      |