

## Colony - Issues

| #    | Tracker     | Status     | Priority | Subject   | Assignee      | Updated             | Category              | % Done |
|------|-------------|------------|----------|---|---------------|---------------------|-----------------------|--------|
| 1457 | Task        | Wontfix    | Low      | Work on battery detection                             | Alex Zirbel   | 11/09/2011 12:17 AM | Autonomous Recharging | 0      |
| 338  | Task        | Wontfix    | Tabled   | Program Bayboard EEPROM                               | Austin Buchan | 09/30/2010 07:54 PM | Autonomous Recharging | 0      |
| 314  | Task        | Worksforme | High     | Send Charging Board Documents to Kevin                | Brad Neuman   | 03/21/2009 12:48 PM | Autonomous Recharging | 0      |
| 303  | Bug         | Fixed      | Normal   | Bayboard orb and beacons can't be on at the same time | Austin Buchan | 03/21/2009 12:48 PM | Autonomous Recharging | 0      |
| 293  | Bug         | Wontfix    | Tabled   | fix homing and station detecting on ARCHS             | Emily Hart    | 09/30/2010 07:53 PM | Autonomous Recharging | 0      |
| 273  | Task        | Fixed      | Low      | Bay Board I2C   | Evan Mullinix | 03/21/2009 12:48 PM | Autonomous Recharging | 0      |
| 241  | Enhancement | Fixed      | Low      | Video From ColoNet GUI                                | Greg Tress    | 03/21/2009 12:48 PM | Autonomous Recharging | 0      |
| 238  | Task        | Worksforme | Normal   | Recharging Demo                                       | Chris Mar     | 03/21/2009 12:48 PM | Autonomous Recharging | 0      |
| 231  | Bug         | Fixed      | Low      | Resolve ARCHS inductor problem                        | Brad Neuman   | 03/21/2009 12:48 PM | Autonomous Recharging | 0      |