

Colony Scout - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated	Category	% Done
2110	Bug	Assigned	Normal	BOM returns values even when IR LED cannot possibly permeate through the material it is enclosed by.	Thomas Mullins	11/11/2012 02:56 PM		0
1848	Task	Wontfix	Normal	Coverage Testing	Thomas Mullins	03/24/2013 04:34 PM	EE Hardware	0
1846	Task	Fixed	Normal	Test 2 BOMS	Thomas Mullins	03/24/2013 04:34 PM	EE Hardware	0
2056	Bug	Fixed	Normal	Fix and test 2nd sonar on scout_avr	Thomas Mullins	08/28/2012 05:52 PM		100
1849	Task	Fixed	Normal	Proximity Test	Thomas Mullins	12/05/2011 06:27 PM	EE Hardware	100
1845	Task	Fixed	Normal	Single BOM Test	Thomas Mullins	12/01/2011 04:49 PM	EE Hardware	100
1827	Task	Fixed	Low	Create ROS Node: AVR Bridge	Thomas Mullins	04/03/2012 04:16 PM	OS	100