

Colony Scout - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated	Category	% Done
1801	Task	Fixed	Normal	Call Freeman Supply about Color Mixing	Dan Shope	10/10/2011 12:00 PM	Mechanical	0
1799	Enhancement	Fixed	Normal	Setup support@colonyscout.com	Dan Shope	10/10/2011 04:02 PM	Administrative	100
1793	Task	Fixed	Normal	Create mockup for Cliff Sensor Testing	Dan Shope	10/07/2011 10:51 PM	Mechanical	0
1791	Task	Fixed	Normal	Fastener Purchasing	Dan Shope	10/09/2011 03:07 PM	Administrative	0
1536	Task	Fixed	Normal	Add WhereUsed category to inventory db	Dan Shope	10/24/2010 12:20 AM	Administrative	0
1517	Bug	Fixed	Normal	Lower tolerance on baseplates	Dan Shope	11/16/2010 08:34 AM	Mechanical	0
1516	Bug	Fixed	High	Test rocker switch for 4A sustained power	Dan Shope	10/27/2010 03:30 PM	Mechanical	0
1485	Enhancement	Fixed	Normal	Viability of switching Gyros (larger range, faster, cheaper, smaller)	Dan Shope	10/05/2011 03:43 PM	Scoutfly	0
1482	Bug	Fixed	Normal	Purchase equipment for surface mount soldering	Dan Shope	10/23/2010 05:05 AM	Administrative	0
1470	Task	Fixed	Normal	Design bending check parts	Dan Shope	10/16/2010 03:57 PM	Mechanical	50
1468	Task	Fixed	Normal	Purchase storage bins for electrical and mechanical parts	Dan Shope	10/23/2010 05:05 AM	Administrative	80
1459	Bug	Fixed	Normal	resize breakfly power traces	Dan Shope	10/02/2010 02:02 PM	Breakfly	0
1425	Task	Fixed	Normal	Find new battery supplier	Dan Shope	10/09/2010 12:18 AM	Mechanical	0
1381	Task	Fixed	Normal	acquire ATmega 128RFA1 chips	Dan Shope	09/21/2010 09:13 PM	Scoutfly	0
1095	Bug	Fixed	Normal	ColonyScout Mail Server	Dan Shope	02/10/2010 11:55 PM		0
1085	Task	Fixed	Normal	Get the BreakFly Dimensions and positioning	Dan Shope	02/09/2010 06:52 PM	Mechanical	0
1047	Task	Fixed	Normal	Team Member Bios	Dan Shope	01/29/2010 11:11 AM		0
976	Task	Fixed	Normal	Scoutfly Connectors	Dan Shope	01/20/2010 05:14 PM	Scoutfly	0
974	Task	Fixed	Normal	Accessory Ball Bearing	Dan Shope	10/01/2010 03:51 PM	Mechanical	80
512	Task	Fixed	Normal	Backup Files into Repository	Dan Shope	06/02/2009 09:10 PM		100
510	Bug	Fixed	Normal	Add encoder access holes to SolidWorks Model	Dan Shope	07/22/2009 01:58 PM		0