

## Colony Scout - Issues

| #    | Tracker | Status   | Priority | Subject  | Assignee       | Updated             | Category | % Done |
|------|---------|----------|----------|--|----------------|---------------------|----------|--------|
| 2109 | Bug     | Assigned | Normal   | Add Fuel Guage and Protection circuit to charge board  | Julian Binder  | 11/11/2012 03:31 PM |          | 0      |
| 2110 | Bug     | Assigned | Normal   | BOM returns values even when IR LED cannot possibly permeate through the material it is enclosed by. | Thomas Mullins | 11/11/2012 02:56 PM |          | 0      |
| 1993 | Task    | Fixed    | Normal   | Design Forklift in Solidworks  | Yuyang Guo     | 09/18/2012 02:00 PM |          | 100    |