

## Colony Scout - Issues

| #    | Tracker | Status   | Priority | Subject  | Assignee      | Updated             | Category       | % Done |
|------|---------|----------|----------|--|---------------|---------------------|----------------|--------|
| 1777 | Task    | Fixed    | High     | Parts Order for Fall Prototype Testing               | Priyanka Deo  | 10/23/2011 02:29 AM | Administrative | 100    |
| 1511 | Task    | Fixed    | High     | Probes for small SMT parts                           | Chris Mar     | 10/23/2010 11:43 PM | Scoutfly       | 0      |
| 844  | Task    | Wontfix  | High     | Bootloader   | Brad Neuman   | 09/21/2010 09:13 PM | OS             | 0      |
| 1907 | Task    | Assigned | Normal   | Check speaker magnet interference with IMU/Compass   | Dan Jacobs    | 11/07/2011 04:48 PM | EE Hardware    | 0      |
| 978  | Task    | Assigned | Normal   | System Wiring  | Dan Shope     | 10/23/2011 08:23 AM | Scoutfly       | 40     |
| 1789 | Task    | Fixed    | Normal   | Test Cliff Sensors                                   | Alexander Lam | 10/16/2011 09:43 PM | Administrative | 100    |
| 1798 | Task    | Assigned | Normal   | Mechanical Work Log                                  | Dan Shope     | 10/15/2011 12:39 PM | Mechanical     | 20     |
| 1793 | Task    | Fixed    | Normal   | Create mockup for Cliff Sensor Testing               | Dan Shope     | 10/07/2011 10:51 PM | Mechanical     | 0      |
| 1536 | Task    | Fixed    | Normal   | Add WhereUsed category to inventory db               | Dan Shope     | 10/24/2010 12:20 AM | Administrative | 0      |
| 975  | Task    | Wontfix  | Normal   | Hood Buttons   | Dan Shope     | 10/04/2010 03:12 AM | Mechanical     | 0      |
| 1087 | Task    | Fixed    | Normal   | Design Breakfly                                      | Rohan Aletty  | 10/04/2010 03:10 AM | Breakfly       | 90     |
| 974  | Task    | Fixed    | Normal   | Accessory Ball Bearing                               | Dan Shope     | 10/01/2010 03:51 PM | Mechanical     | 80     |
| 1381 | Task    | Fixed    | Normal   | acquire ATmega 128RFA1 chips                         | Dan Shope     | 09/21/2010 09:13 PM | Scoutfly       | 0      |
| 1086 | Task    | Invalid  | Normal   | Design debug board                                   | Emily Hart    | 07/29/2010 07:19 PM | Scoutfly       | 0      |
| 1018 | Task    | Fixed    | Normal   | Test motor backdrive                                 | Kevin Woo     | 07/29/2010 07:18 PM | Scoutfly       | 0      |
| 1097 | Task    | Fixed    | Normal   | Email Steve about bootstrapping ARM                  | Kevin Woo     | 02/10/2010 04:17 PM | OS             | 100    |
| 1085 | Task    | Fixed    | Normal   | Get the BreakFly Dimensions and positioning          | Dan Shope     | 02/09/2010 06:52 PM | Mechanical     | 0      |
| 970  | Task    | Fixed    | Normal   | Find all resistors we need                           | Kevin Woo     | 02/06/2010 09:05 PM | Scoutfly       | 0      |
| 1037 | Task    | Fixed    | Normal   | Put 50MHz oscillator on the ethernet phy chip        | Kevin Woo     | 02/05/2010 11:16 PM | Scoutfly       | 0      |
| 1045 | Task    | Fixed    | Normal   | Add a USB A port to the board on the host controller | Kevin Woo     | 02/05/2010 11:11 PM | Scoutfly       | 0      |
| 1036 | Task    | Invalid  | Normal   | Doublecheck SDRAM footprint                          | Kevin Woo     | 01/26/2010 11:28 PM | Scoutfly       | 0      |
| 1038 | Task    | Fixed    | Normal   | Modify Power supply                                  | Kevin Woo     | 01/22/2010 08:24 PM | Scoutfly       | 0      |
| 976  | Task    | Fixed    | Normal   | Scoutfly Connectors                                  | Dan Shope     | 01/20/2010 05:14 PM | Scoutfly       | 0      |
| 1023 | Task    | Fixed    | Normal   | Double check ARM Analog VDD supply voltage           | Kevin Woo     | 01/19/2010 02:31 PM | Scoutfly       | 0      |
| 969  | Task    | Fixed    | Normal   | Look for smaller ethernet connector                  | Kevin Woo     | 01/15/2010 10:55 PM | Scoutfly       | 0      |
| 987  | Task    | Fixed    | Normal   | Jumper on Power Kill Line                            | Kevin Woo     | 01/14/2010 12:54 AM | Scoutfly       | 0      |
| 993  | Task    | Assigned | Normal   | Look into accelerometer speed                        | Brad Neuman   | 01/13/2010 09:40 PM | Scoutfly       | 0      |
| 968  | Task    | Fixed    | Normal   | Double-check Resistor Divider Values                 | Kevin Woo     | 01/13/2010 08:15 PM | Scoutfly       | 0      |
| 967  | Task    | Fixed    | Normal   | Double-check IC Footprints                           | Kevin Woo     | 01/13/2010 12:24 AM | Scoutfly       | 0      |
| 973  | Task    | Fixed    | Normal   | Share schematic + board on dropbox with dan          | Kevin Woo     | 01/12/2010 05:34 AM | Scoutfly       | 0      |
| 1046 | Task    | Fixed    | Low      | Update BOM   | Kevin Woo     | 02/06/2010 09:15 PM | Scoutfly       | 0      |

| #   | Tracker | Status  | Priority | Subject             | Assignee   | Updated             | Category | % Done |
|-----|---------|---------|----------|---------------------|------------|---------------------|----------|--------|
| 997 | Task    | Wontfix | Tabled   | Spec out microphone | James Kong | 10/16/2010 03:58 PM | Scoutfly | 0      |