

## Colony Scout - Issues

| #    | Tracker | Status  | Priority | Subject   | Assignee    | Updated             | Category | % Done |
|------|---------|---------|----------|---|-------------|---------------------|----------|--------|
| 981  | Bug     | Fixed   | Normal   | Modify accessory ports                              | Kevin Woo   | 01/13/2010 08:25 PM | Scoutfly | 0      |
| 982  | Bug     | Fixed   | Normal   | Add UART for the BOM                                | Kevin Woo   | 01/13/2010 08:24 PM | Scoutfly | 0      |
| 983  | Bug     | Fixed   | Normal   | Add micro a/b usb-otg connector                     | Kevin Woo   | 01/15/2010 10:00 PM | Scoutfly | 0      |
| 984  | Bug     | Fixed   | Normal   | Add ffc connectors to the board to replace cgrids   | Kevin Woo   | 01/14/2010 02:42 AM | Scoutfly | 0      |
| 985  | Bug     | Fixed   | Normal   | Add RX/TX UART pin bypass to the AVR for debugging  | Kevin Woo   | 01/13/2010 08:22 PM | Scoutfly | 0      |
| 988  | Bug     | Fixed   | Normal   | Jumper on USB data line to ARM                      | Kevin Woo   | 01/16/2010 04:00 PM | Scoutfly | 0      |
| 989  | Bug     | Fixed   | Normal   | Test point on 2 test clocks on ARM                  | Kevin Woo   | 01/14/2010 12:59 AM | Scoutfly | 0      |
| 991  | Bug     | Fixed   | Normal   | Remove AVR reset and replace with IO from ARM       | Kevin Woo   | 01/14/2010 12:53 AM | Scoutfly | 0      |
| 992  | Bug     | Fixed   | Normal   | Pin out rest of AVR ADC                             | Kevin Woo   | 01/14/2010 02:42 AM | Scoutfly | 0      |
| 994  | Bug     | Fixed   | Normal   | Hook up Gyro PD and ST through level shifter to AVR | Kevin Woo   | 01/14/2010 12:48 AM | Scoutfly | 0      |
| 995  | Bug     | Fixed   | Normal   | Put wireless amp enable lines on ARM                | Kevin Woo   | 01/14/2010 12:49 AM | Scoutfly | 0      |
| 1004 | Bug     | Fixed   | Normal   | Split power into input and output connectors        | Kevin Woo   | 01/15/2010 04:55 PM | Scoutfly | 0      |
| 1005 | Bug     | Fixed   | Normal   | Move pushbutton to ffc                              | Kevin Woo   | 01/15/2010 04:58 PM | Scoutfly | 0      |
| 1013 | Bug     | Fixed   | Normal   | Circuit simulate LEDs                               | Kevin Woo   | 01/16/2010 12:22 AM | Scoutfly | 0      |
| 1021 | Bug     | Fixed   | Normal   | I2C Level shifter on the AVR I2C lines              | Kevin Woo   | 01/19/2010 02:16 PM | Scoutfly | 0      |
| 1022 | Bug     | Fixed   | Normal   | Replace hex schmitt triggers with duals             | Kevin Woo   | 01/19/2010 02:28 PM | Scoutfly | 0      |
| 1032 | Bug     | Fixed   | Normal   | Part Change   | Kevin Woo   | 02/05/2010 11:21 PM | Scoutfly | 0      |
| 1035 | Bug     | Fixed   | Normal   | Redo decoupling caps on ARM                         | Kevin Woo   | 01/22/2010 05:20 PM | Scoutfly | 0      |
| 1044 | Bug     | Fixed   | Normal   | Choose a new rtc backup battery                     | Kevin Woo   | 02/06/2010 09:04 PM | Scoutfly | 0      |
| 1385 | Bug     | Fixed   | Normal   | Scoutfly mounting holes to ground plane             | Kevin Woo   | 10/01/2010 03:51 PM | Scoutfly | 0      |
| 1806 | Bug     | Wontfix | Normal   | Gumstix Memory Change                               | Jeff Cooper | 03/22/2013 06:38 PM | Scoutfly | 100    |