

## Colony Scout - Issues

| #    | Tracker | Status   | Priority | Subject  | Assignee        | Updated             | Category | % Done |
|------|---------|----------|----------|--|-----------------|---------------------|----------|--------|
| 2121 | Bug     | Assigned | Normal   | File Error Service call  | Alex Zirbel     | 11/16/2012 06:12 PM |          | 0      |
| 2110 | Bug     | Assigned | Normal   | BOM returns values even when IR LED cannot possibly permeate through the material it is enclosed by. | Thomas Mullins  | 11/11/2012 02:56 PM |          | 0      |
| 2109 | Bug     | Assigned | Normal   | Add Fuel Guage and Protection circuit to charge board  | Julian Binder   | 11/11/2012 03:31 PM |          | 0      |
| 1878 | Bug     | Assigned | Normal   | Cliff Detection  | Lalitha Ganesan | 10/26/2011 06:07 PM | OS       | 0      |
| 1807 | Bug     | Assigned | Normal   | Website Work Log   | Dan Shope       | 10/15/2011 07:12 PM | Website  | 80     |
| 1547 | Bug     | Assigned | Normal   | Fix Encoder pinout on breakfly   | Abraham Levkoy  | 10/05/2011 05:53 PM | Breakfly | 0      |