

## Colony Scout - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated	Category	% Done
2121	Bug	Assigned	Normal	File Error Service call	Alex Zirbel	11/16/2012 06:12 PM		0
2110	Bug	Assigned	Normal	BOM returns values even when IR LED cannot possibly permeate through the material it is enclosed by.	Thomas Mullins	11/11/2012 02:56 PM		0
2109	Bug	Assigned	Normal	Add Fuel Guage and Protection circuit to charge board	Julian Binder	11/11/2012 03:31 PM		0
1878	Bug	Assigned	Normal	Cliff Detection	Lalitha Ganesan	10/26/2011 06:07 PM	OS	0
1807	Bug	Assigned	Normal	Website Work Log	Dan Shope	10/15/2011 07:12 PM	Website	80
1547	Bug	Assigned	Normal	Fix Encoder pinout on breakfly	Abraham Levkoy	10/05/2011 05:53 PM	Breakfly	0