

Colony - Bug #231

Resolve ARCHS inductor problem

02/05/2008 12:08 PM - Brad Neuman

Status:	Fixed	Start date:	
Priority:	Low	Due date:	
Assignee:	Brad Neuman	% Done:	0%
Category:	Autonomous Recharging	Estimated time:	0.00 hour
Target version:	Autonomous Recharging		
Description			
change the inductor values to obtain a continuous mode power converter and get stable battery readings			

History

#3 - 03/21/2009 12:45 PM - Rich Hong

- Status changed from 5 to Fixed

#4 - 03/21/2009 12:48 PM - Rich Hong

- Category set to Autonomous Recharging