

Tooltron - Issues

| # | Tracker | Status | Priority | Subject | Assignee | Updated | Category | % Done |
|------|-------------|------------|----------|--|-----------|---------------------|----------|--------|
| 1359 | Bug | Fixed | Normal | Green button on the wood bandsaw is stuck | Kevin Woo | 05/12/2010 09:09 PM | | 0 |
| 1358 | Bug | Fixed | Normal | cable on wood bandsaw seems broken | Kevin Woo | 05/12/2010 09:11 PM | | 0 |
| 1356 | Bug | Fixed | High | Tool 3 resetting | Kevin Woo | 05/12/2010 09:08 PM | | 0 |
| 1353 | Task | Fixed | Normal | test Nicos cable | Kevin Woo | 05/11/2010 02:41 PM | | 0 |
| 1352 | Task | Fixed | Normal | redo cable ties | Kevin Woo | 05/11/2010 02:41 PM | | 0 |
| 1348 | Task | Fixed | Normal | reprogram bootloaders to deal with eeprom | Kevin Woo | 05/12/2010 09:10 PM | | 0 |
| 1233 | Bug | Fixed | High | Cardbox hangs | Kevin Woo | 04/09/2010 09:21 PM | | 0 |
| 1200 | Task | Duplicate | Normal | Update state machine interactions between cardbox and server | Kevin Woo | 04/09/2010 09:22 PM | | 0 |
| 1151 | Bug | Fixed | High | input/output error | Kevin Woo | 04/21/2010 02:45 PM | | 50 |
| 1150 | Bug | Worksforme | Normal | Fix USB issue with RS485 chip on cardbox schematic/layout | Kevin Woo | 03/27/2010 08:47 PM | | 0 |
| 1142 | Task | Worksforme | Normal | Hot glue connectors in the two bandsaws | Kevin Woo | 03/27/2010 08:52 PM | | 50 |
| 1140 | Enhancement | Fixed | Normal | Tool ping packet | Kevin Woo | 03/03/2010 08:39 PM | | 0 |
| 1137 | Task | Fixed | Normal | Modify rs482 connector for cardbox | Kevin Woo | 03/04/2010 11:47 PM | | 0 |
| 1132 | Enhancement | Wontfix | Normal | Add a FUSE section to the bootloader | Kevin Woo | 02/24/2010 06:22 PM | | 0 |
| 1130 | Bug | Fixed | Normal | add compiler directive to prevent stack junk | Kevin Woo | 02/24/2010 05:53 PM | | 0 |
| 1128 | Enhancement | Fixed | Normal | Reorganize repository to share common code | Kevin Woo | 02/24/2010 01:14 AM | | 0 |
| 1126 | Task | Fixed | Normal | Test new cardbox board | Kevin Woo | 03/04/2010 12:46 AM | | 0 |
| 1125 | Task | Fixed | Normal | Cut usb cable to make new cardbox cable | Kevin Woo | 02/27/2010 02:25 PM | | 0 |
| 1124 | Task | Fixed | Normal | Jump table for user code | Kevin Woo | 02/28/2010 05:00 PM | | 0 |
| 1123 | Task | Fixed | Normal | clear user code jump when programming | Kevin Woo | 02/23/2010 09:57 PM | | 0 |
| 1122 | Task | Fixed | Normal | Send nacks | Kevin Woo | 02/23/2010 09:58 PM | | 0 |
| 1120 | Task | Fixed | Normal | Packet handler timeouts | Kevin Woo | 02/23/2010 09:29 PM | | 0 |
| 1119 | Task | Fixed | Normal | Watchdog Reset | Kevin Woo | 02/23/2010 11:14 PM | | 100 |
| 1104 | Bug | Fixed | Normal | Remove magic number from uart init | Kevin Woo | 03/01/2010 02:40 AM | | 0 |
| 1103 | Bug | Fixed | Normal | Tools send wrong Ack message | Kevin Woo | 03/01/2010 02:42 AM | | 0 |
| 1090 | Task | Wontfix | Normal | Buy OR gates | Kevin Woo | 02/23/2010 08:37 PM | | 0 |
| 1089 | Enhancement | Fixed | Normal | New Cardbox Board | Kevin Woo | 02/23/2010 08:37 PM | | 0 |
| 1057 | Bug | Fixed | Normal | yellow warning light blinks too slowly | Kevin Woo | 01/28/2010 02:03 PM | | 0 |
| 980 | Bug | Fixed | High | debug tool board 3 | Kevin Woo | 01/18/2010 06:45 PM | | 0 |
| 501 | Task | Fixed | High | Update Wiki | Kevin Woo | 09/23/2009 11:18 PM | | 100 |