

## Issues

| #   | Project | Tracker | Status   | Priority | Subject                     | Assignee         | Updated             | Category              | % Done |
|-----|---------|---------|----------|----------|-----------------------------|------------------|---------------------|-----------------------|--------|
| 299 | Colony  | Bug     | Invalid  | High     | SPI failure                 | Eugene Marinelli | 03/21/2009 12:50 PM | Library               | 0      |
| 300 | Colony  | Bug     | Fixed    | High     | SPI failure                 | Brad Neuman      | 03/21/2009 12:50 PM | Library               | 0      |
| 557 | Colony  | Bug     | Fixed    | Urgent   | Batteries                   | Jimmy Bourne     | 09/10/2009 04:53 PM | Hardware              | 100    |
| 558 | Colony  | Bug     | Fixed    | Urgent   | USB Cables                  | Jimmy Bourne     | 09/10/2009 04:52 PM | Hardware              | 100    |
| 575 | Colony  | Bug     | Assigned | Tabled   | Battery Level Indicator     | John Sexton      | 09/30/2010 08:00 PM | Library               | 0      |
| 242 | Colony  | Task    | Fixed    | Tabled   | LCD module                  | Austin Buchan    | 04/10/2009 05:04 PM | Hardware              | 0      |
| 273 | Colony  | Task    | Fixed    | Low      | Bay Board I2C               | Evan Mullinix    | 03/21/2009 12:48 PM | Autonomous Recharging | 0      |
| 329 | Colony  | Task    | Fixed    | High     | Program all robot's EEPROMs | Brad Neuman      | 03/21/2009 12:49 PM | Hardware              | 0      |