

Colony Scout - Bug #1013

Circuit simulate LEDs

01/15/2010 04:56 PM - Kevin Woo

Status:	Fixed	Start date:	01/15/2010
Priority:	Normal	Due date:	
Assignee:	Kevin Woo	% Done:	0%
Category:	Scoutfly	Estimated time:	0.00 hour
Target version:	Development		
Description			
Make sure that we don't need resistors on the base and not blow the ARMs current limit			

History

#1 - 01/16/2010 12:22 AM - Kevin Woo
- Status changed from Assigned to Fixed

updated resistor values and changed circuits for the leds accordingly