

Colony Scout - Task #1038

Modify Power supply

01/22/2010 03:07 AM - Kevin Woo

Status:	Fixed	Start date:	01/22/2010
Priority:	Normal	Due date:	
Assignee:	Kevin Woo	% Done:	0%
Category:	Scoutfly	Estimated time:	0.00 hour
Target version:	Development		
Description			
<ul style="list-style-type: none">• The ARM needs the voltages to be sequenced.• Eliminated the 1.2V domain			

History

#1 - 01/22/2010 08:24 PM - Kevin Woo

- Status changed from Assigned to Fixed