

Colony - Task #174

BOM 1.5 driver

01/20/2008 07:22 PM - Eugene Marinelli

Status:	Fixed	Start date:	
Priority:	Low	Due date:	
Assignee:	Austin Buchan	% Done:	0%
Category:	Library	Estimated time:	0.00 hour
Target version:	Library		
Description			
BOM 1.5 driver			

History

#1 - 01/16/2009 06:11 PM - Kevin Woo

Needs double checking.

#2 - 02/25/2009 05:27 PM - Austin Buchan

- Status changed from Assigned to 5

Doublecheck complete. Robots with the same hex code but different BOM types function correctly.

#3 - 03/07/2009 11:46 PM - Kevin Woo

- Tracker changed from Enhancement to Task

#4 - 03/21/2009 12:41 PM - Rich Hong

- Status changed from 5 to Fixed

#5 - 03/21/2009 12:42 PM - Rich Hong

- Category set to Library