

Colony Scout - Bug #995

Put wireless amp enable lines on ARM

01/13/2010 09:45 PM - Rich Hong

Status:	Fixed	Start date:	01/13/2010
Priority:	Normal	Due date:	
Assignee:	Kevin Woo	% Done:	0%
Category:	Scoutfly	Estimated time:	0.00 hour
Target version:	Development		
Description			
PAEN to EN and send it to the ARM			

History

#1 - 01/14/2010 12:49 AM - Kevin Woo

- Status changed from Assigned to Fixed