	2014-2				201	4-3			2014-4					2014-5					2014-6					2014-7						
	Π	6	7	8	9	1	10	11	12	13	14	-	15	16	17	18	3   1	9	20	21	22	23	24	25	26	27	28	3 29	3 3	0
Colony		Cò	lon	ý																		-								
Battery Level Indicator																														
Improve library error codes																														
Better sanity check for invalid BOM type																														
XBee/Wireless Initialization																														
get all the library inti's and functions ()																														
Xbee Documentation																														
xbee baud rates																														
Wireless - core send, ack functions																														
Wireless - xbee.c																														
xbee id		_																												
Conclusion on filter design			-		0%																									
Figure out rangefinders group			-		0%																									
Complete SURG form			-		0%																									
Check/Order robot battery clips		As	sigr	ned	50%																									
Line Follower Collimator																														
Redo robot pants																														
Get Colony videos onto VideoTron. Embed in ()																														
Clean up repository branches																														
Add Line Following to Library																														
Profile different mapping surfaces																														
Make Hunter-Prey Ref More Verbose																														
Clean up Colony-New and prepare for next ()																														
Implement Intersection Behavior																														
wl_basic_do_default(int *length) doesn't ()																														
Schedule Fleet Maintenence Day																														
Discuss and Contact about Extra Colony III ()																														
Colony - Hardware																														

Investigate how to use the JTAG ICE	
Colony - Library	
Make sure all robots program the correct ()	
Colony Scout	Colony Scout
Colony Environment	
Software Architecture	
<b>Reflow Oven Temperature Regulation</b>	
Update Boards on Eagle	
Research PCB Assemby Costing	
Website Work Log	
Video for Scout Intro	
Create ROS Node: Buttons	Assigned 100%
Create ROS Node: Timer	Assigned 100%
Create ROS Node: IMU	Assigned 0%
Create ROS Node: Accessory	Assigned 100%
Create ROS Node: Encoders	Assigned 100%
Create ROS Node: Wireless	Assigned 0%
Create ROS Node: USB Serial	Assigned 80%
Create ROS Node: Cliffsensors	Assigned 100%
Create ROS Node: BOM	Assigned 90%
Create ROS Node: Analog	Assigned 0%
BOM Interference Testing	Assigned 0%
BOM Driver Code	Assigned 0%
Sonar Wiring	Assigned 0%
Sonar Position Tracking	
Send Sonar Readings to ARM	
Automate Stepping and Sonar Reading	
Sonar on ARM	
Make ARM command Sonar on AVR	
Read IMU values and send to ARM	Assigned 0%
Pose Estimation	Assigned 0%
Control Motors (ARM)	Assigned 10%
Track Encoders	
Charging Base	

Create Scout Chassis	
IMU on ARM	Assigned 0%
ROSSERIAL on ARM	Assigned 0%
CliffSensor on ARM	Assigned 0%
Create Transmitting Protocal	Assigned 0%
Wireless on ARM	Assigned 10%
Cliff Detection	Assigned 0%
Buttons on ARM	Assigned 0%
USB Serial on ARM	Assigned 0%
Power Up Rest of Scoutfly	
Get Old Boards and Funding Info	
Test AVR on ARM	Assigned 0%
Get Sonar Stepping and Reading	Assigned 0%
"Automated" Turning	Assigned 0%
Add Fuel Guage and Protection circuit ()	
BOM returns values even when IR LED ()	
File Error Service call	
Colony Scout - 1.0	
BOM Send/Receive Functions	
Assembly Instructions	
Fix Encoder pinout on breakfly	
Colony Scout - 1.2	
NanoRK Wireless Library	
Loook @ Robostix AVR<->ARM Comms ()	
Electronics Purchasing, OCT-08	Assigned 0%
Colony Scout - Development	
System Wiring	
Look into accelerometer speed	
Email Red W	Assigned 0%
Create roboclub demo	Assigned 50%
Design SmartFly Smart Acessory ()	
Mechanical Work Log	Assigned 20%
Check speaker magnet interference ()	
Lo	НуLо

type proposed proposal	Assigned 0%						
Meeting							
Mechanical Logic Gates	Mechanical Logic Gates						
Update - website	Assigned 0%						
You Tube + Display Case	Assigned 0%						
Website - host on roboclub	Assigned 0%						
Wishlist							
Compressed Air System							
Quadrotor	Quadrotor						
Fix the Quadrotor							
Point Cloud Display							
Design aluminum frame for Quad1	Assigned 0%						
Make private repository							
Email Harrison to Order Parts							
USB to micro USB cable							
RobOrchestra	RobOrchestra						
Model Solenoids for brassbot in Solidworks	Assigned 0%						
Get Pianobot modelled with the piano	Assigned 0%						
Tooltron							
Write tutorial about network programming							
Tooltron - 1.0							
script for network programming							
notifications of tool boot packets in ()							
Document the Network Bootloader							
Document the States of the toolbox/cardbox							
Server dies when internet is out							
update server docs							
Tooltron - 1.1							
timeouts not working correctly							
remove server hacks							
organize repo							
Document new Error codes on Cardbox							
order more boards and replace drill-press ()							
Tooltron - 2.0							

MySQL Stored Procedures	
Underwater Swarm Bots	Underwater Swarm Bots
FTDI cable	Assigned 0%
WCTU	WCTU
WCTU - WCTU Version 1.0	WCTU -WCTU Version 1.0 50%
	Assigned 0%
Create v1.0 JS Client Revision 1	