

## Colony - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated	Category	% Done
1458	Task	Assigned	Tabled	Redo robot pants	Austin Buchan	10/01/2010 05:40 PM	Hardware	0
445	Task	Wontfix	Normal	Test Orb Driver Code	Austin Buchan	09/30/2010 09:05 PM	Library	0
338	Task	Wontfix	Tabled	Program Bayboard EEPROM	Austin Buchan	09/30/2010 07:54 PM	Autonomous Recharging	0
351	Task	Wontfix	Tabled	Add bayboard and chargeboard status table	Austin Buchan	09/30/2010 07:53 PM	Hardware	0
490	Task	Fixed	Normal	Spec out new wheels for the robot	Austin Buchan	09/10/2009 04:54 PM	Hardware	100
242	Task	Fixed	Tabled	LCD module	Austin Buchan	04/10/2009 05:04 PM	Hardware	0
341	Task	Worksforme	Normal	Mimic BOM LED Circuit for Diagnostic Station	Austin Buchan	04/08/2009 11:41 PM	Diagnostic Station	100
344	Task	Worksforme	Normal	Construct New LED Circuit to Mimic IR LED Current on BOM Boards	Austin Buchan	04/08/2009 11:40 PM	Diagnostic Station	100
306	Bug	Fixed	Tabled	BOM 1.5 Shift register error	Austin Buchan	03/21/2009 12:50 PM	Library	0
174	Task	Fixed	Low	BOM 1.5 driver	Austin Buchan	03/21/2009 12:50 PM	Library	0
303	Bug	Fixed	Normal	Bayboard orb and beacons can't be on at the same time	Austin Buchan	03/21/2009 12:48 PM	Autonomous Recharging	0
316	Task	Fixed	High	SURG S09 Application	Austin Buchan	03/21/2009 12:47 PM	Administration	0
175	Task	Fixed	Normal	F08 SURG application	Austin Buchan	03/21/2009 12:42 PM	Administration	0