## Colony - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated	Category	% Done
303	Bug	Fixed	Normal	Bayboard orb and beacons can't be on at the same time	Austin Buchan	03/21/2009 12:48 PM	Autonomous Recharging	0
273	Task	Fixed	Low	Bay Board I2C	Evan Mullinix	03/21/2009 12:48 PM	Autonomous Recharging	0
241	Enhancement	Fixed	Low	Video From ColoNet GUI	Greg Tress	03/21/2009 12:48 PM	Autonomous Recharging	0
231	Bug	Fixed	Low	Resolve ARCHS inductor problem	Brad Neuman	03/21/2009 12:48 PM	Autonomous Recharging	0
1457	Task	Wontfix	Low	Work on battery detection	Alex Zirbel	11/09/2011 12:17 AM	Autonomous Recharging	0
338	Task	Wontfix	Tabled	Program Bayboard EEPROM	Austin Buchan	09/30/2010 07:54 PM	Autonomous Recharging	0
293	Bug	Wontfix	Tabled	fix homing and station detecting on ARCHS	Emily Hart	09/30/2010 07:53 PM	Autonomous Recharging	0
314	Task	Worksforme	High	Send Charging Board Documents to Kevin	Brad Neuman	03/21/2009 12:48 PM	Autonomous Recharging	0
238	Task	Worksforme	Normal	Recharging Demo	Chris Mar	03/21/2009 12:48 PM	Autonomous Recharging	0

04/25/2024 1/1