Colony - Issues

| # | Tracker | Status | Priority | Subject | Assignee | Updated | Category | % Done |
|------|-------------|------------|----------|---|---------------|---------------------|-----------------------|--------|
| 1457 | Task | Wontfix | Low | Work on battery detection | Alex Zirbel | 11/09/2011 12:17 AM | Autonomous Recharging | 0 |
| 338 | Task | Wontfix | Tabled | Program Bayboard EEPROM | Austin Buchan | 09/30/2010 07:54 PM | Autonomous Recharging | 0 |
| 293 | Bug | Wontfix | Tabled | fix homing and station detecting on ARCHS | Emily Hart | 09/30/2010 07:53 PM | Autonomous Recharging | 0 |
| 231 | Bug | Fixed | Low | Resolve ARCHS inductor problem | Brad Neuman | 03/21/2009 12:48 PM | Autonomous Recharging | 0 |
| 238 | Task | Worksforme | Normal | Recharging Demo | Chris Mar | 03/21/2009 12:48 PM | Autonomous Recharging | 0 |
| 241 | Enhancement | Fixed | Low | Video From ColoNet GUI | Greg Tress | 03/21/2009 12:48 PM | Autonomous Recharging | 0 |
| 273 | Task | Fixed | Low | Bay Board I2C | Evan Mullinix | 03/21/2009 12:48 PM | Autonomous Recharging | 0 |
| 303 | Bug | Fixed | Normal | Bayboard orb and beacons can't be on at the same time | Austin Buchan | 03/21/2009 12:48 PM | Autonomous Recharging | 0 |
| 314 | Task | Worksforme | High | Send Charging Board Documents to Kevin | Brad Neuman | 03/21/2009 12:48 PM | Autonomous Recharging | 0 |