

Colony - Issues

| # | Tracker | Status | Priority | Subject | Assignee | Updated | Category | % Done |
|-----|-------------|------------|----------|---|------------------|---------------------|----------|--------|
| 797 | Bug | Wontfix | Tabled | rename motor.h | Alex Zirbel | 11/09/2011 12:15 AM | Library | 0 |
| 571 | Bug | Wontfix | Low | Remove spaces in repository | Alex Zirbel | 11/09/2011 12:15 AM | Library | 0 |
| 562 | Bug | Duplicate | Tabled | Fix init functions | Brad Neuman | 10/02/2010 07:15 PM | Library | 0 |
| 575 | Bug | Assigned | Tabled | Battery Level Indicator | John Sexton | 09/30/2010 08:00 PM | Library | 0 |
| 418 | Bug | Wontfix | Normal | Fix Rangefinder numbering | Rich Hong | 09/25/2010 03:19 PM | Library | 0 |
| 305 | Bug | Wontfix | Normal | Wireless - number of robots in token ring doesn't report right number | Brian Coltin | 09/24/2010 01:51 PM | Library | 0 |
| 560 | Bug | Fixed | High | BOM and rangefinder donot work together | James Kong | 09/09/2009 10:32 PM | Library | 0 |
| 509 | Bug | Fixed | Urgent | Fix doxygen links | Kevin Woo | 09/07/2009 07:50 PM | Library | 0 |
| 306 | Bug | Fixed | Tabled | BOM 1.5 Shift register error | Austin Buchan | 03/21/2009 12:50 PM | Library | 0 |
| 300 | Bug | Fixed | High | SPI failure | Brad Neuman | 03/21/2009 12:50 PM | Library | 0 |
| 299 | Bug | Invalid | High | SPI failure | Eugene Marinelli | 03/21/2009 12:50 PM | Library | 0 |
| 294 | Bug | Worksforme | Normal | wireless library not thread safe | Brian Coltin | 03/21/2009 12:50 PM | Library | 0 |
| 291 | Bug | Fixed | Low | dragonfly_lib | Kevin Woo | 03/21/2009 12:50 PM | Library | 0 |
| 290 | Bug | Fixed | Low | redundant calls of sei | Kevin Woo | 03/21/2009 12:50 PM | Library | 0 |
| 289 | Bug | Fixed | High | Fix analog code | James Kong | 03/21/2009 12:50 PM | Library | 0 |
| 202 | Bug | Invalid | High | Analog Port | Kevin Woo | 03/21/2009 12:50 PM | Library | 0 |
| 798 | Enhancement | Assigned | Normal | get all the library inti's and functions to behave | Brad Neuman | 10/02/2010 07:13 PM | Library | 30 |
| 578 | Enhancement | Wontfix | Tabled | usb_put* function with fixed width | Ben Wasserman | 10/01/2010 05:28 PM | Library | 0 |
| 577 | Enhancement | Assigned | Tabled | Improve library error codes | Brad Neuman | 09/30/2010 08:25 PM | Library | 0 |
| 263 | Enhancement | Wontfix | Tabled | Fixed point library | | 09/30/2010 07:48 PM | Library | 0 |
| 388 | Enhancement | Wontfix | Low | Make RTC more granular and adjustable | Martin Herrmann | 09/25/2010 03:09 PM | Library | 0 |
| 195 | Enhancement | Fixed | Normal | improve lights.c | Martin Herrmann | 09/16/2010 07:11 PM | Library | 100 |
| 856 | Enhancement | Fixed | Normal | Makefile Update | David Schultz | 11/27/2009 12:57 PM | Library | 100 |
| 194 | Enhancement | Wontfix | Tabled | improve lcd.c | Kevin Woo | 08/31/2009 09:00 PM | Library | 0 |
| 190 | Enhancement | Wontfix | Tabled | fix buzzer.c | Kevin Woo | 08/31/2009 09:00 PM | Library | 0 |
| 315 | Enhancement | Wontfix | Low | Joystick control cleanup | Bradley Yoo | 03/21/2009 12:50 PM | Library | 0 |
| 309 | Enhancement | Fixed | High | Make 1 source for library files | Brian Coltin | 03/21/2009 12:50 PM | Library | 0 |
| 304 | Enhancement | Invalid | Low | Rangefinders code distance comments | Brad Neuman | 03/21/2009 12:50 PM | Library | 0 |
| 302 | Enhancement | Fixed | Low | Encoders documentation | Justin Scheiner | 03/21/2009 12:50 PM | Library | 0 |
| 230 | Enhancement | Worksforme | Normal | More Friendly Makefile for Library Work | Brian Coltin | 03/21/2009 12:50 PM | Library | 0 |
| 214 | Enhancement | Fixed | Normal | Wrapper functions for backwards compatability on BOM | Chris Mar | 03/21/2009 12:50 PM | Library | 0 |

| # | Tracker | Status | Priority | Subject | Assignee | Updated | Category | % Done |
|-----|-------------|----------|----------|---|-----------------|---------------------|----------|--------|
| 203 | Enhancement | Wontfix | Low | I2C Multimaster for USI port | Kevin Woo | 03/21/2009 12:50 PM | Library | 0 |
| 193 | Enhancement | Wontfix | Low | improve i2c.c | Kevin Woo | 03/21/2009 12:50 PM | Library | 0 |
| 192 | Enhancement | Fixed | Low | improve dragonfly_lib.c | Kevin Woo | 03/21/2009 12:50 PM | Library | 0 |
| 191 | Enhancement | Fixed | Low | improve dio.c | Kevin Woo | 03/21/2009 12:50 PM | Library | 0 |
| 189 | Enhancement | Fixed | Tabled | improve bom.c | James Kong | 03/21/2009 12:50 PM | Library | 0 |
| 188 | Enhancement | Fixed | Low | improve battery.c | Kevin Woo | 03/21/2009 12:50 PM | Library | 0 |
| 187 | Enhancement | Fixed | Normal | improve analog.c | Kevin Woo | 03/21/2009 12:50 PM | Library | 0 |
| 368 | Task | Assigned | Tabled | Make sure all robots program the correct xbee id from eeprom | Brian Coltin | 10/02/2010 07:24 PM | Library | 0 |
| 337 | Task | Wontfix | High | Update Wireless Maximum Number of XBees | Brian Coltin | 10/02/2010 07:11 PM | Library | 0 |
| 445 | Task | Wontfix | Normal | Test Orb Driver Code | Austin Buchan | 09/30/2010 09:05 PM | Library | 0 |
| 308 | Task | Wontfix | High | Wireless - merge the bayboard and dragonfly versions | Brian Coltin | 09/30/2010 08:36 PM | Library | 0 |
| 569 | Task | Invalid | Normal | comment eeprom.c | Brad Neuman | 09/30/2010 08:24 PM | Library | 0 |
| 391 | Task | Wontfix | Normal | Investigate and profile the avr-libc floating point emulation | Brad Neuman | 09/25/2010 03:18 PM | Library | 0 |
| 724 | Task | Fixed | Low | Remove function inlining TODO tags from wireless library | David Schultz | 10/23/2009 05:02 PM | Library | 0 |
| 307 | Task | Fixed | Low | Merge encoders into the trunk | Justin Scheiner | 03/21/2009 12:50 PM | Library | 0 |
| 301 | Task | Fixed | Low | Fix analog8.c doxygen comments | Kevin Woo | 03/21/2009 12:50 PM | Library | 0 |
| 240 | Task | Fixed | Tabled | delay_ms rewrite | Kevin Woo | 03/21/2009 12:50 PM | Library | 0 |
| 197 | Task | Fixed | Normal | Test SPI driver | Ben Poole | 03/21/2009 12:50 PM | Library | 0 |
| 180 | Task | Fixed | Normal | Add analog8 to trunk | Kevin Woo | 03/21/2009 12:50 PM | Library | 0 |
| 174 | Task | Fixed | Low | BOM 1.5 driver | Austin Buchan | 03/21/2009 12:50 PM | Library | 0 |