

## Colony - Issues

| #    | Tracker     | Status   | Priority | Subject  | Assignee      | Updated             | Category           | % Done |
|------|-------------|----------|----------|--|---------------|---------------------|--------------------|--------|
| 1568 | Task        | Assigned | Tabled   | Clean up Colony-New and prepare for next year                                      | John Sexton   | 11/08/2010 10:48 PM | Administration     | 0      |
| 1466 | Task        | Assigned | Low      | Clean up repository branches   | John Sexton   | 10/10/2010 12:38 AM | Administration     | 10     |
| 1400 | Task        | Assigned | Low      | Complete SURG form   | John Sexton   | 09/07/2010 05:49 PM | Administration     | 0      |
| 1903 | Enhancement | Assigned | Normal   | Discuss and Contact about Extra Colony III Boards                                  | Priyanka Deo  | 11/16/2011 08:24 PM | Administration     | 50     |
| 1464 | Task        | Assigned | Normal   | Get Colony videos onto VideoTron. Embed in website.                                | Nico Paris    | 01/17/2011 03:42 PM | Administration     | 80     |
| 1576 | Task        | Assigned | Normal   | Schedule Fleet Maintenance Day   | Ben Wasserman | 11/18/2010 09:03 PM | Administration     | 50     |
| 320  | Enhancement | New      | Tabled   | Automatically update robot status page with testing station                        |               | 03/21/2009 12:55 PM | Diagnostic Station | 0      |
| 693  | Bug         | Assigned | Tabled   | Better sanity check for invalid BOM type   | John Sexton   | 10/01/2010 05:45 PM | Hardware           | 0      |
| 1439 | Task        | Assigned | Normal   | Check/Order robot battery clips  | Nico Paris    | 11/17/2010 03:41 PM | Hardware           | 50     |
| 1387 | Task        | Assigned | Normal   | Conclusion on filter design  | John Sexton   | 09/03/2010 11:39 PM | Hardware           | 0      |
| 237  | Enhancement | Feedback | Tabled   | Design Dragonfly Replacement Board   |               | 03/21/2009 12:54 PM | Hardware           | 0      |
| 1389 | Task        | Assigned | Normal   | Figure out rangefinders group  | John Sexton   | 09/03/2010 11:39 PM | Hardware           | 0      |
| 390  | Task        | Feedback | Tabled   | Investigate how to use the JTAG ICE  | Nico Paris    | 09/24/2009 11:08 AM | Hardware           | 0      |
| 1453 | Task        | Assigned | Tabled   | Line Follower Collimator   | Megan Dority  | 10/12/2010 07:56 PM | Hardware           | 0      |
| 1458 | Task        | Assigned | Tabled   | Redo robot pants   | Austin Buchan | 10/01/2010 05:40 PM | Hardware           | 0      |
| 1562 | Task        | Assigned | Low      | Make Hunter-Prey Ref More Verbose  | Ben Wasserman | 11/12/2010 05:11 PM | Introductory Labs  | 0      |
| 575  | Bug         | Assigned | Tabled   | Battery Level Indicator  | John Sexton   | 09/30/2010 08:00 PM | Library            | 0      |
| 798  | Enhancement | Assigned | Normal   | get all the library inti's and functions to behave                                 | Brad Neuman   | 10/02/2010 07:13 PM | Library            | 30     |
| 577  | Enhancement | Assigned | Tabled   | Improve library error codes  | Brad Neuman   | 09/30/2010 08:25 PM | Library            | 0      |
| 368  | Task        | Assigned | Tabled   | Make sure all robots program the correct xbee id from eeprom                       | Brian Coltin  | 10/02/2010 07:24 PM | Library            | 0      |
| 964  | Task        | Feedback | Tabled   | investigate new AVR simulator?   |               | 12/18/2009 07:30 AM | Simulator          | 0      |
| 1534 | Task        | Assigned | High     | Add Line Following to Library  | Ben Wasserman | 11/16/2010 12:55 AM | Traffic Navigation | 70     |
| 1570 | Task        | Assigned | Normal   | Implement Intersection Behavior  | Ben Wasserman | 11/19/2010 04:57 PM | Traffic Navigation | 30     |
| 1556 | Task        | Assigned | Normal   | Profile different mapping surfaces   | Willis Chang  | 12/03/2010 05:01 PM | Traffic Navigation | 90     |
| 1574 | Bug         | Assigned | Normal   | wl_basic_do_default(int *length) doesn't set *length to zero if no packet received | Ben Wasserman | 11/11/2010 09:37 PM | Traffic Navigation | 0      |
| 946  | Task        | Assigned | Low      | Wireless - core send, ack functions  | Ben Wasserman | 10/02/2010 07:17 PM | Wireless           | 90     |
| 950  | Task        | Assigned | Low      | Wireless - xbee.c  | Ben Wasserman | 10/02/2010 07:18 PM | Wireless           | 80     |
| 925  | Enhancement | Assigned | Low      | xbee baud rates  | Ben Wasserman | 09/30/2010 09:27 PM | Wireless           | 90     |
| 852  | Bug         | Assigned | Low      | Xbee Documentation   | Priyanka Deo  | 11/09/2011 12:17 AM | Wireless           | 0      |
| 960  | Bug         | Assigned | Low      | xbee id  | Ben Wasserman | 09/30/2010 09:26 PM | Wireless           | 0      |
| 790  | Bug         | Assigned | Normal   | XBee/Wireless Initialization   | Brad Neuman   | 10/02/2010 07:16 PM | Wireless           | 0      |