Colony

	20)16·	6			20	16-7			2	016-8	3			20	16-9	9			201	6-10			20	16-1	1
	23	24	25	26	6 27	28	3 29	30	31	32	33	34	35	5 3	6 ;	37	38	39	40	41	42	43	44	45	46	47
Colony	Cold	ny				-																				
Battery Level Indicator																										
Improve library error codes																										
Better sanity check for invalid BOM type																										
XBee/Wireless Initialization																										
get all the library inti's and functions ()																										
Xbee Documentation																										
xbee baud rates																										
Wireless - core send, ack functions																										
Wireless - xbee.c																										
xbee id																										
Conclusion on filter design		-	ed 0%																							
Figure out rangefinders group		-	ed 0%																							
Complete SURG form		-	ed 0%																							
Check/Order robot battery clips	Assi	gne	ed 50	%																						
Line Follower Collimator																										
Redo robot pants																										
Get Colony videos onto VideoTron. Embed in ()																										
Clean up repository branches																										
Add Line Following to Library																										
Profile different mapping surfaces																										
Make Hunter-Prey Ref More Verbose																										
Clean up Colony-New and prepare for next ()																										
Implement Intersection Behavior																										
wl_basic_do_default(int *length) doesn't ()																										
Schedule Fleet Maintenence Day																										
Discuss and Contact about Extra Colony III ()																										
Colony - Hardware																										

Investigate how to use the JTAG ICE
olony - Library
Make sure all robots program the correct ()