## **Colony Scout - Issues**

#	Tracker	Status	Priority	Subject	Assignee	Updated	Category	% Done
2110	Bug	Assigned		BOM returns values even when IR LED cannot possibly permeate through the material it is enclosed by.	Thomas Mullins	11/11/2012 02:56 PM		0

05/08/2024 1/1