

Tooltron - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated	Category	% Done
1177	Bug	Duplicate	Normal	cosmic bit flips		03/27/2010 08:55 PM		0
1273	Bug	Invalid	Normal	fix error messages on bas sync	Brad Neuman	05/10/2010 06:13 PM		0
1204	Bug	Fixed	Normal	MySQL server goes away	Brad Neuman	04/09/2010 09:21 PM		0
1188	Bug	Fixed	Normal	tooltron does not check if members have paid dues	Brad Neuman	05/11/2010 08:19 PM		80
1179	Bug	Fixed	High	Tool ACL issues	Brad Neuman	03/27/2010 03:36 PM		0
1166	Bug	Invalid	Normal	use ip instead of domain name in tooltron	Brad Neuman	11/01/2011 03:26 PM		0
1164	Bug	Fixed	High	fix ERROR emails	Brad Neuman	05/20/2010 03:51 PM		20
1157	Bug	Duplicate	Low	make tooltron log files split	Brad Neuman	03/23/2010 06:00 PM		0
1152	Bug	Fixed	High	idiot mode exploit	Brad Neuman	03/23/2010 05:59 PM		0
1133	Bug	Fixed	Normal	Tool and server take wrong turnon message	Brad Neuman	03/01/2010 02:41 AM		0
1131	Bug	Fixed	Normal	network programming script sends 1 too many packets	Brad Neuman	02/28/2010 03:31 PM		0
1121	Bug	Fixed	Normal	Update netprog to deal with errors	Brad Neuman	03/01/2010 02:41 AM		0
1056	Bug	Fixed	High	fix dangerous "left on" case	Brad Neuman	01/28/2010 02:03 PM		0
979	Bug	Fixed	High	tooltron server doesn't properly handle dead lines	Brad Neuman	01/18/2010 06:45 PM		0
556	Bug	Fixed	Normal	tool tron bolts	Jimmy Bourne	09/08/2009 07:45 PM		100
1359	Bug	Fixed	Normal	Green button on the wood bandsaw is stuck	Kevin Woo	05/12/2010 09:09 PM		0
1358	Bug	Fixed	Normal	cable on wood bandsaw seems broken	Kevin Woo	05/12/2010 09:11 PM		0
1356	Bug	Fixed	High	Tool 3 resetting	Kevin Woo	05/12/2010 09:08 PM		0
1233	Bug	Fixed	High	Cardbox hangs	Kevin Woo	04/09/2010 09:21 PM		0
1151	Bug	Fixed	High	input/output error	Kevin Woo	04/21/2010 02:45 PM		50
1150	Bug	Worksforme	Normal	Fix USB issue with RS485 chip on cardbox schematic/layout	Kevin Woo	03/27/2010 08:47 PM		0
1130	Bug	Fixed	Normal	add compiler directive to prevent stack junk	Kevin Woo	02/24/2010 05:53 PM		0
1104	Bug	Fixed	Normal	Remove magic number from uart init	Kevin Woo	03/01/2010 02:40 AM		0
1103	Bug	Fixed	Normal	Tools send wrong Ack message	Kevin Woo	03/01/2010 02:42 AM		0
1057	Bug	Fixed	Normal	yellow warning light blinks too slowly	Kevin Woo	01/28/2010 02:03 PM		0
980	Bug	Fixed	High	debug tool board 3	Kevin Woo	01/18/2010 06:45 PM		0
1539	Bug	Invalid	Normal	Broken	Nico Paris	12/07/2010 05:29 PM		0
1900	Bug	Fixed	Normal	Log Filehandle	R W	04/09/2012 02:32 PM		0